

China State Construction Engineering (Hong Kong) Ltd.

Contract No. CV/2007/03

Development at Anderson Road – Site Formation and Associated Infrastructure Works

Quarterly EM&A Summary Report for September 2012 – November 2012

January 2013

		Name	Signature
Prepared & Checked:		Isabella Yeung	Pe
Reviewed, Approved Certified:	&	Edith Ng (ETL)	Tagtaling

Version: 0	Data	11 lanuar	. 2012
Version. U	Date.	14 January	/ 2013

Disclaimer

This report is prepared for China State Construction Engineering (Hong Kong) Ltd. and is given for its sole benefit in relation to and pursuant to Contract No. CV/2007/03 Development at Anderson Road – Site Formation and Associated Infrastructure Works and may not be disclosed to, quoted to or relied upon by any person other than China State Construction Engineering (Hong Kong) Ltd. without our prior written consent. No person (other than China State Construction Engineering (Hong Kong) Ltd.) into whose possession a copy of this report comes may rely on this report without our express written consent and China State Construction Engineering (Hong Kong) Ltd. may not rely on it for any purpose other than as described above.

AECOM Asia Co. Ltd.

11/F, Grand Central Plaza, Tower 2, 138 Shatin Rural Committee Road, Shatin, NT, Hong Kong. Tel: (852) 3105 8686 Fax: (852) 2317 7609 www.aecom.com



Ref.: OAPANDSNEM00 0 0975L.13

21 January 2013

By Fax (3656 3100 / 2407 8382) and Post

Engineer's Representative Ove Arup & Partners Level 5, Festival Walk 80 Tat Chee Avenue Kowloon Tong, Kowloon Hong Kong

Attention: Mr. Dennis Leung

Dear Sir,

Re: Contract No. CV/2007/03 (Environmental Permit No. EP -140/2002)
Development at Anderson Road
Site Formation and Associated Infrastructure Works
Quarterly EM&A Report for September to November 2012

Reference is made to the Environmental Team's submission of the draft Quarterly EM&A Report for September to November 2012 received by E-mail on 14 January 2013.

Please be informed that we have no adverse comment on the captioned submission.

Thank you very much for your kind attention and please do not hesitate to contact the undersigned should you have any queries.

Yours sincerely,

David Yeung

Independent Environmental Checker

c.c. AECOM

Attn: Ms. Edith Ng

CSCEC

Attn: Mr. Wilson Lau

Fax: 2891 0305

Fax: 2702 6553

Q:\Projects\OAPANDSNEM00\Corr\OAPANDSNEM00 0 0975L.13.doc

Table of Content

EXE	CUTIVE	SUMMARY1
1	INTR	ODUCTION5
	1.1 1.2 1.3	Scope of Report
2	SUMI	MARY OF EM&A PROGRAMME REQUIREMENTS7
	2.1 2.2 2.3	Monitoring Parameters
3	MON	ITORING RESULTS8
	3.1 3.2 3.3	Air Quality
4	ADVI	CE ON SOLID AND LIQUID WASTE MANAGEMENT STATUS14
	4.1	Summary of Solid and Liquid Waste Management
5	SUMI	MARY OF NON-COMPLIANCE (EXCEEDANCES) OF ENVIRONMENTAL QUALITY 15
	5.1	Summary of Exceedances and Review of the Reasons for Non-compliance
6	СОМ	PLAINT, NOTIFICATION OF SUMMONS AND SUCCESSFUL PROSECUTION 16
	6.1	Summary of Environmental complaints, notification of summons and successful prosecutions
7	СОМ	MENTS, RECOMMENDATIONS AND CONCLUSIONS18
	7.1 7.2 7.3	Comments on Mitigation Measures

List of Tables

Table 1.1	Contact Information of Key Personnel
Table 3.1	Summary of Number of Exceedances for 1-hr and 24-hr TSP Concentration
Table 3.2	Summary of Number of Exceedances for Construction Noise
Table 4.1	Summary of Quantity of Waste for Disposal
Table 6.1	Summary of Environmental Complaints, Summons and Prosecutions

List of Figures

Figure 1.1	General Layout Plan
Figure 2.1	Monitoring Locations

List of Appendices

Appendix A	Project Organization Structure
Appendix B	Implementation Schedule of Environmental Mitigation Measures (EMIS)
Appendix C	Summary of Action and Limit Levels
Appendix D	Graphical Presentation of Impact Air Quality Monitoring Results over the Past Four
	Months
Appendix E	Graphical Presentation of Noise Monitoring Results over the Past Four Months
Appendix F	Cumulative Statistics on Exceedances, Complaints, Notification of Summons and
	Successful Prosecutions

EXECUTIVE SUMMARY

The Project "Development at Anderson Road – Site Formation and Associated Infrastructure Works" (hereafter called "the Project") is proposed to form platforms for housing development and associated uses in area of about 20 hectares, and to carry out necessary infrastructural upgrading or improvement works to cater for the proposed development.

China State Construction Engineering (Hong Kong) Limited (CSCE) was commissioned as the Contractor of the Project. AECOM Asia Co. Ltd. (AECOM) was employed by CSCE as the Environmental Team (ET) to undertake the Environmental Monitoring and Audit (EM&A) works for the Project.

The impact EM&A for the Project includes air quality and noise monitoring. The EM&A programme for Sau Ming Primary School (ID 4) and Sau Mau Ping Catholic Primary School (ID 5) commenced on 1 May 2008, while for Kwun Tong Government Secondary School (ID 1A), On Yat House (ID 2) and Sau Nga House (ID 3) commenced on 1 June 2008.

The monitoring stations ID 4 & ID 5 will serve both the entire Development of Anderson Road (Schedule 3 Designated Project (DP)) project as well as the Widening of Po Lam Road (Schedule 2 DP) project.

The construction for the Widening of Po Lam Road (Schedule 2 DP) project was commenced in this reporting period, i.e. on 21 September 2011.

This report documents the findings of EM&A works for ID 1A, ID 2, ID 3, ID 4 and ID 5 conducted in the period from 1 September 2012 to 30 November 2012. As informed by the Contractor, construction activities in the reporting quarter were:

- Blasting:
- Drainage works;
- Slope upgrading works:
- Excavation work at Portions A, B, C, D, E, H, J4, S1a, S2a, S2b;
- Temporary traffic arrangement at J/O Po Lam Road & Sau Mau Ping Road, Portion J2, J3 and J4;
- Site clearance:
- Erection of hoardings and chain link fence;
- Establishment of temporary access and temporary drainage;
- Slope stabilization;
- Tree transplanting and protection;
- Maintenance works:
- Bridge structural works;
- Retaining structures structural works;
- RE wall panel installation;
- Slope drainage and maintenance access;
- · Erection and maintenance of blasting cages and fencing;
- Pre-stressing works of bridge;
- Toe / Beam planter construction;
- Permanent backfilling at RW22;
- Bored pile(column method), capping beam & panel wall construction at R15;
- Lowering down of bored pile at R15;
- Construction of Bridge A, B and D;
- U-channel and box-culvert works at Portion D and E; and
- Preparation works for area J1a and J1b (R15b)

Environmental Monitoring Works

EM&A Programme

A summary of monitoring and audit activities conducted in the reporting quarter is listed below:

24-hour TSP monitoring16 sessions1-hour TSP monitoring48 sessionsDaytime Noise monitoring13 sessionsEnvironmental Site Inspection13 sessions

Breaches of Action and Limit Levels

No exceedance of Action and Limit Level was recorded for 1-hour TSP and 24-hour TSP monitoring in the reporting quarter.

According to the information provided by the Contractor, one (1) Action Level exceedance was recorded since one (1) noise related complaint was received in the reporting quarter.

No exceedance Limit Level of noise was recorded in the reporting quarter.

Complaint, Notification of Summons and Successful Prosecution

According to the information provided by the Contractor, two (2) air complaints which received in August 2012 and one (1) noise related complaint which received in October 2012 were recorded in Monthly EM&A Report for September and October 2012 respectively. No notification of summons and successful prosecution were received in the reporting quarter.

• CEDD referred a complaint about dust nuisance along the road at Clear Water Bay Road near Anderson Road crossing on 31 August 2012.

Fugitive dust emission was potentially generated from the vehicles passing the haul roads at Portion J2. Water spraying has been carried out by water truck twice daily to minimize fugitive emission generated.

According to the routine 1-hour TSP and 24-hour TSP monitoring data recorded at the nearest monitoring station ID 1A (roof of Kwun Tong Government Secondary School) on 28 August 2012, the measured 24-hour TSP level was found to be 79μg/m³. The measured 1-hour TSP levels on 28 August 2012 were found to be 80.2μg/m³; 78.5μg/m³ and 79.9μg/m³ respectively. All measured 1-hour TSP and 24-hour TSP level were below the Action and Limit Level.

Despite that the 1-hour and 24-hour TSP levels were below the Action and Limit level. The Contractor was recommended to ensure the wheel washing facility was operated at the construction site entrance and closely monitor the effectiveness of the wheel washing facility.

No further complaint was received and the complaint was closed.

 A complaint was referred by CEDD (ICC) regarding the fugitive dust impact at the slope of Shun Chi Court on 31 August 2012.

Fugitive dust emission was potentially generated from the works area at the slope of Shun Chi Court. The works area has been covered by tarpaulin sheet and frequent watering have been carried out to minimize fugitive emission generated.

According to the routine 1-hour TSP and 24-hour TSP monitoring data recorded at the nearest monitoring station ID 1A (roof of Kwun Tong Government Secondary School) on 28 August 2012, the measured 24-hour TSP level was found to be 79µg/m³. The measured 1-hour TSP levels on 28 August 2012 were found to be 80.2µg/m³; 78.5µg/m³ and 79.9µg/m³ respectively. All measured 1-hour TSP and 24-hour TSP level were below the Action and Limit Level.

Despite that the 1-hour and 24-hour TSP levels were below the Action and Limit level. The Contractor was recommended to apply regular water spray to the works area and closely monitor the status of tarpaulin sheet to minimize fugitive emission generated.

No further complaint was received and the complaint was closed.

 A complaint was sent to CSCE regarding the construction noise impact in Portion S1a on 15 October 2012 via email.

According to the noise monitoring data recorded on 8 and 19 October 2012 at the nearest monitoring station ID5 (Sau Mau Ping Catholic Primary School), the measured noise level in Leq (30-min) were 63.2dB(A) and 62.6dB(A) respectively, which were below the Limit Level.

As advised by the Contractor, no construction activities involving the use of Powered Mechanical Equipment (PME), e.g. rock breaking or rock drilling works, were conducted in the concerned area in October 2012. Construction noise was potentially contributed by rock breaking activities of other projects at works area in Portion D and E nearby.

Although the complaint was not considered as project related, the Contractor was recommended to stipulate the following noise mitigation measures in case any construction activities involving the use of PME is conducted in the concerned area: rock breaking works should be stopped at 6pm, the noise mitigation measures should be maintained and the effectiveness of noise mitigation measures deployed within works area should be reviewed onsite regularly in order to provide sufficient noise screening effect properly for the noise sensitive receivers.

No further complaint was received and the complaint was closed.

Please refer to the monthly EM&A report (September 2012 Version 0 and October 2012 Version 0) accordingly for the details of the captioned complaint.

1 INTRODUCTION

1.1 Scope of Report

- 1.1.1 This is the quarterly Environmental Monitoring and Audit (EM&A) Report for the reporting period from 1 September 2012 to 30 November 2012 under the Project "Contract CV/2007/03 Development at Anderson Road Site Formation and Associated Infrastructure Works" (hereafter called "the Project"), which serving for both the entire Development of Anderson Road (Schedule 3 Designated Project (DP)) project as well as the Widening of Po Lam Road (Schedule 2 DP) project (which was commenced on 21 September 2011).
- 1.1.2 This report presents a summary of the EM&A works, list of activities and mitigation measures proposed by the Environmental Team (ET) for the Project during the reporting period.

1.2 Project Organization

1.2.1 The project organization structure is shown in Appendix A. The key personnel contact names and numbers are summarized in Table 1.1.

Table 1.1 Contact Information of Key Personnel

Party	Position	Name	Telephone	Fax
	Chief Resident Engineer	Dennis Leung	3656 3000	3656 3100
ER (Ove Arup)	Senior Resident Engineer	Michael Wright	3656 3000	3656 3100
	Resident Engineer (Safety and Environmental)	Kenneth Lee	3656 3000	3656 3100
IEC (ENVIRON)	Independent Environmental Checker	David Yeung	3743 0717	3548 6988
Contractor	Site Agent	Wilson Lau	2704 2095	2702 6553
(CSCE)	Environmental Manager	Leo Chung	2704 2095	2702 6553
ET (AECOM)	ET Leader	Edith Ng	3922 9407	2317 7609

1.3 Summary of Construction Works

- 1.3.1 The Contactor has carried out major activities in the reporting quarter. Details of the works undertaken in this reporting period are listed below:
 - Blasting;
 - Drainage works;
 - Slope upgrading works;
 - Excavation work at Portions A, B, C, D, E, H, J4, S1a, S2a, S2b;
 - Temporary traffic arrangement at J/O Po Lam Road & Sau Mau Ping Road, Portion J2, J3 and J4;
 - Site clearance;
 - Erection of hoardings and chain link fence;
 - Establishment of temporary access and temporary drainage;
 - Slope stabilization;
 - Tree transplanting and protection;
 - Maintenance works:
 - Bridge structural works;
 - Retaining structures structural works;
 - RE wall panel installation;

- Slope drainage and maintenance access;
- Erection and maintenance of blasting cages and fencing;
- Pre-stressing works of bridge;
- Toe / Beam planter construction;
- Permanent backfilling at RW22;
- Bored pile(column method), capping beam & panel wall construction at R15;
- Lowering down of bored pile at R15;
- Construction of Bridge A, B and D;
- U-channel and box-culvert works at Portion D and E; and
- Preparation works for area J1a and J1b (R15b)
- 1.3.2 The general layout plan of the Project site showing the contract area is shown in Figure 1.1.
- 1.3.3 The environmental mitigation measures implementation schedule (EMIS) are presented in Appendix B.

2 SUMMARY OF EM&A PROGRAMME REQUIREMENTS

2.1 Monitoring Parameters

- 2.1.1 The EM&A Manual designated five monitoring stations to monitor environmental impacts on air quality and noise due to the Project. The monitoring locations are depicted in Figure 2.1.
- 2.1.2 The monitoring stations ID 4 & ID 5 will serve both the entire Development of Anderson Road (Schedule 3 Designated Project (DP)) project as well as the Widening of Po Lam Road (Schedule 2 DP) project.

2.2 Environmental Quality Performance Limits (Action/Limit Levels)

- 2.2.1 The environmental quality performance limits (i.e. Action/Limit Levels) were derived from the baseline air quality and noise monitoring results of Kwun Tong Government Secondary School (ID 1A), On Yat House (ID 2), Sau Nga House (ID 3), Sau Ming Primary School (ID 4) and Sau Mau Ping Catholic Primary School (ID 5) and / or as defined in the EM&A Manual for air quality and noise impacts.
- 2.2.2 The baseline condition of air quality (for ID 1A, ID 2 & ID 3) in the Project site was reviewed in August 2008 upon agreed by ER and IEC. Reviewed Action Levels for air quality at ID 1A, ID 2 and ID 3 were established in September 2008. The latest Action and Limit Levels (established in September 2008) for all monitoring parameters are summarized in Appendix C.

2.3 Environmental Mitigation Measures

2.3.1 Relevant environmental mitigation measures were stipulated in the Particular Specification and EP (No.: EP-140/2002) for the Contractor to adopt. A list of environmental mitigation measures and their implementation statuses are given in Appendix B.

AECOM Asia Co. Ltd. 7 December 2012

3 MONITORING RESULTS

3.1 Air Quality

- 3.1.1 Air quality monitoring, including 1-hr and 24-hr TSP, was conducted for at least three times every 6 days and for at least once every 6 days respectively at the 5 monitoring stations (ID 1A, ID 2, ID 3, ID 4 and ID 5), in accordance with the EM&A Manual.
- 3.1.2 Forty-eighth (48) sessions of 1-hr TSP monitoring and sixteen (16) sessions of 24-hr TSP monitoring were conducted for the 5 monitoring stations (ID 1A, ID 2, ID 3, ID4 & ID5) in the reporting quarter.
- 3.1.3 The weather was mostly sunny, with occasionally cloudy period in the reporting quarter. The trend of impact air quality monitoring results for the reporting quarter is given in Appendix D. Major dust source included construction activities of the Project, concurrent construction activities of another project carried out in the vicinity and nearby traffic emissions.
- 3.1.4 No exceedance of Action and Limit Level was recorded for 1-hour TSP and 24-hour TSP monitoring in the reporting quarter.
- 3.1.5 Table 3.1 presents the number of exceedances recorded in each month of the reporting quarter. The number of monitoring events included regular impact monitoring events and additional ones, if any.

Table 3.1 Summary of Number of Exceedances for 1-hr and 24-hr TSP Concentration

Monitoring	Location	Level of Exceedance	Month			
Parameter			Sep 12	Oct 12	Nov 12	
1-hr TSP	ID 1A	No. of monitoring events	15	18	15	
		Action	0	0	0	
	.	Limit	0	0	0	
	ID 2	No. of monitoring events	15	18	15	
		Action	0	0	0	
		Limit	0	0	0	
	ID 3	No. of monitoring events	15	18	15	
		Action	0	0	0	
		Limit	0	0	0	
	ID 4	No. of monitoring events	15	18	15	
		Action	0	0	0	
		Limit	0	0	0	
	ID 5	No. of monitoring events	15	18	15	
		Action	0	0	0	
		Limit	0	0	0	
		Total	0	0	0	
24-hr TSP	ID 1A	Total No. of monitoring events	0 5	0	0 5	
24-hr TSP	ID 1A					
24-hr TSP	ID 1A	No. of monitoring events	5	6	5	
24-hr TSP	ID 1A	No. of monitoring events Action	5	6	5	
24-hr TSP		No. of monitoring events Action Limit	5 0 0	6 0 0	5 0 0	
24-hr TSP		No. of monitoring events Action Limit No. of monitoring events	5 0 0 5	6 0 0 6	5 0 0 5	
24-hr TSP		No. of monitoring events Action Limit No. of monitoring events Action	5 0 0 5	6 0 0 6	5 0 0 5	
24-hr TSP	ID 2	No. of monitoring events Action Limit No. of monitoring events Action Limit	5 0 0 5 0	6 0 0 6 0	5 0 0 5 0	
24-hr TSP	ID 2	No. of monitoring events Action Limit No. of monitoring events Action Limit No. of monitoring events Action Limit Limit Action Limit	5 0 0 5 0 0 5	6 0 0 6 0 0	5 0 0 5 0 0	
24-hr TSP	ID 2	No. of monitoring events Action Limit No. of monitoring events Action Limit No. of monitoring events Action Action	5 0 0 5 0 5 0	6 0 0 6 0 0 6	5 0 0 5 0 0 5	
24-hr TSP	ID 2	No. of monitoring events Action Limit No. of monitoring events Action Limit No. of monitoring events Action Limit Limit Action Limit	5 0 0 5 0 0 5 0	6 0 0 6 0 0 6 0	5 0 0 5 0 0 5 0	
24-hr TSP	ID 2	No. of monitoring events Action Limit No. of monitoring events Limit No. of monitoring events Action Limit	5 0 0 5 0 5 0 0 5 0	6 0 0 6 0 6 0	5 0 0 5 0 0 5 0	
24-hr TSP	ID 2	No. of monitoring events Action Limit No. of monitoring events	5 0 0 5 0 0 5 0 0 5	6 0 0 6 0 6 0 0 6	5 0 0 5 0 0 5 0 0 5	
24-hr TSP	ID 2	No. of monitoring events Action Limit No. of monitoring events	5 0 0 5 0 5 0 0 5 0	6 0 0 6 0 6 0 0 6	5 0 0 5 0 5 0 0 5 0	
24-hr TSP	ID 2	No. of monitoring events Action Limit No. of monitoring events	5 0 0 5 0 5 0 0 5 0 0 5	6 0 0 6 0 0 6 0 0 6	5 0 0 5 0 5 0 0 5 0 0 5	

3.2 Construction Noise

- 3.2.1 Noise was conducted at the 5 monitoring stations (ID 1A, ID 2, ID 3, ID 4 and ID 5) for at least once per week during the construction phase (0700 1900) of the Project.
- 3.2.2 Thirteen (13) noise monitoring events were carried out for all monitoring stations in the reporting quarter.
- 3.2.3 According to the information provided by the Contractor, one (1) noise complaint was received in the reporting quarter; hence, one (1) Action Level exceedance was received in the reporting quarter.
- 3.2.4 No Limit Level exceedance of noise was recorded in the reporting quarter.
- 3.2.5 The graphical plots of trends of the noise monitoring results in the reporting quarter are provided in Appendix E. Major noise source included construction activities of the Project, concurrent construction activities of another project carried out in the vicinity, nearby traffic emissions and noise from school activities and community noise.
- 3.2.6 Table 3.2 presents the number of exceedances recorded in each month of the reporting quarter. The number of monitoring events included regular monitoring events and additional ones, if any.

Table 3.2 Summary of Number of Exceedances for Construction Noise

Monitoring	Location	Location Level of Exceedance		Month			
Parameter			Sep 12	Oct 12	Nov 12		
Construction	ID 1A	No. of monitoring events	4	5	4		
Noise		Limit	0	0	0		
	ID 2	No. of monitoring events	4	5	4		
		Limit	0	0	0		
	ID 3	No. of monitoring events	4	5	4		
	{	Limit	0	0	0		
	ID 4	No. of monitoring events	4	5	4		
		Limit	0	0	0		
	ID 5	No. of monitoring events	4	5	4		
		Limit	0	0	0		
	To	tal Action Level*	0	1	0		
	To	otal Limit Level	0	0	0		

Remarks: * Number of Action Level exceedance for construction noise is the number of documented noise related complaint received in the reporting period from any one of the sensitive receivers.

3.3 Environmental Site Inspection

- 3.3.1 There were 13 site inspections conducted in the reporting quarter to monitor the implementation of proper environmental pollution control and mitigation measures for the Project. The major concerns for the Project are air quality, noise, water quality and chemical and waste management. Particular observations and non-compliance and their statuses are described below.
- 3.3.2 The Contractor has rectified most of the observations as identified during environmental site inspection in the reporting period within agreed time frame. Rectifications of remaining identified items are undergoing by the Contractor. Follow-up inspections on the status on provision of mitigation measures will be conducted to ensure all identified items are mitigated properly.

3.3.3 Air Quality Impact

- Dusty haul road was observed at Portion J2 (Clear Water Bay Road). The Contractor should provide dust suppressive measure (like provision of regular water spraying or sprinklers) along the haul roads to minimize the dust impact.
- Dark smoke emission was observed from excavator worked at Portion C2. The Contractor should repair the excavators and conduct regular inspection of the working machineries worked in site areas to avoid any dark smoke emission.
- Shelter provided at cement grouting station in works area R15b and soil nailing area in works area R16a were found improper. The Contractor should provide shelter with proper coverage on the top and at the 3 sides for cement grouting station and soil nailing area to minimize fugitive dust emission generated.
- Exposed area and fugitive dust emission was observed in works area at Portion C2. The Contractor should provide regular water spray to the works area and cover up the exposed slopes completely by tarpaulin sheet to minimize fugitive dust emission generated.

3.3.4 Construction Noise Impact

- Absorptive material wrapping to the breaking tips of the breakers working at Portion C2 and S2a works area was found improper. The Contractor should provide proper absorptive material wrapping to the breaking tip of breaker operating in works area prior to rock breaking work.
- Acoustic insulation material which adhered to the noise barriers deployed at R15B was found deteriorated. The Contractor was reminded to inspect the status of the noise barrier regularly and maintain the noise-screening effect.

3.3.5 Water Quality Impact

■ Nil

3.3.6 Chemical and Waste Management

Air compressors, oil drums and chemical containers placed in Bridge A, B, Portion C2, S1a, 16B, Branch M and Barging Point were stored without provision of drip trays. The Contractor should properly store the chemical containers and oil drums within the works area with provision of drip trays in order to retain any oil and chemical leakage.

AECOM Asia Co. Ltd. 12 December 2012

- Drain hole of the drip tray underneath generator placed in Bridge B was found unplugged. The Contractor should plug the drain holes of the drip trays employed on site properly to avoid any oil leakage.
- Chemical containers, recyclable wastes and construction wastes were mixed together in the waste skip located at Portion C2. The Contractor was reminded to implement on-site sorting properly, i.e. recycle wastes whenever possible and dispose containers as chemical waste accordingly.
- Oil stain was found on bare ground under an air compressor and an excavator working in Portion C2 and R16B respectively. The Contractor was reminded to clear the oil stain and dispose as chemical waste.
- Machinery maintenance works in improper works area was observed outside the CSCEC workshop area in Portion S1c. The Contractor should ensure that maintenance works are carried out in roofed, paved and confined works area only.

3.3.7 Landscape and Visual Impact

■ Tree protection net for the retained tree at Bridge A was found loosely installed. The Contractor was reminded to reinstate the tree protection measures and maintain its status.

ADVICE ON SOLID AND LIQUID WASTE MANAGEMENT STATUS

3.4 Summary of Solid and Liquid Waste Management

- 3.4.1 The Contractor is registered as a chemical waste producer for this Project. C&D materials and wastes sorting were carried out on site. Receptacles were available for C&D wastes and general refuse collection.
- 3.4.2 As advised by the Contractor, quantity of waste for disposal in the reporting quarter is summarized in the Table 4.1.

Table 4.1 Summary of Quantity of Waste for Disposal*

Type of weets	Month			
Type of waste	Sep 12	Oct 12	Nov 12	
Total C&D material (m ³)	57,185.27m ³	83,977.00m ³	56,683.28m ³	
Hard Rock and Large Broken Concrete	50,189.79m ³	58,098.00m ³	40,553.72m ³	
Reuse in the Project	6,674.00m ³	25,879.00m ³	0m ³	
Reuse in other Projects	0m ³	0m ³	0m ³	
Disposed to barging point	321.48m ³	0m ³	16,129.56m ³	
Metals	46,860kg	121,280kg	39,340kg	
Paper cardboard packing	10kg	10kg	10kg	
Plastics	10kg	0kg	0kg	
Chemical waste	0L	0L	0L	
General refuse	130.20tonnes	145.22tonnes	188.19tonnes	

^{*}Remarks: The quantity of waste for September, October and November 2012 were updated by the Contractor in December 2012.

- 3.4.3 The Contractor is advised to properly maintain on site C&D materials and wastes collection, sorting and recording system and maximize reuse / recycle of C&D materials and wastes. The Contractor is reminded to properly maintain the site tidiness and dispose of the wastes accumulated on site regularly and properly.
- 3.4.4 The Contractor is reminded that chemical waste containers should be properly treated and stored temporarily in designated chemical waste storage area on site in accordance with the Code of Practise on the Packaging, Labelling and Storage of Chemical Wastes.

4 SUMMARY OF NON-COMPLIANCE (EXCEEDANCES) OF ENVIRONMENTAL QUALITY

- 4.1 Summary of Exceedances and Review of the Reasons for Non-compliance
- 4.1.1 There was no Action and Limit Level exceedance recorded for 1-hr TSP and 24-hr TSP in the reporting quarter.
- 4.1.2 According to the information provided by the Contractor, one (1) noise complaint was received in the reporting quarter. Hence, one (1) Action Level exceedance was received in the reporting quarter.
- 4.1.3 No Limit Level exceedance for noise was recorded at all monitoring stations in the reporting quarter.

5 COMPLAINT, NOTIFICATION OF SUMMONS AND SUCCESSFUL PROSECUTION

5.1 Summary of Environmental complaints, notification of summons and successful prosecutions

- 5.1.1 According to the information provided by the Contractor, two (2) air complaints which received in August 2012 and one (1) noise related complaint which received in October 2012 were recorded in Monthly EM&A Report for September and October 2012 respectively. No notification of summons and successful prosecution were received in the reporting quarter.
 - CEDD referred a complaint about dust nuisance along the road at Clear Water Bay Road near Anderson Road crossing on 31 August 2012.

Fugitive dust emission was potentially generated from the vehicles passing the haul roads at Portion J2. Water spraying has been carried out by water truck twice daily to minimize fugitive emission generated.

According to the routine 1-hour TSP and 24-hour TSP monitoring data recorded at the nearest monitoring station ID 1A (roof of Kwun Tong Government Secondary School) on 28 August 2012, the measured 24-hour TSP level was found to be $79\mu g/m^3$. The measured 1-hour TSP levels on 28 August 2012 were found to be $80.2\mu g/m^3$; $78.5\mu g/m^3$ and $79.9\mu g/m^3$ respectively. All measured 1-hour TSP and 24-hour TSP level were below the Action and Limit Level.

Despite that the 1-hour and 24-hour TSP levels were below the Action and Limit level. The Contractor was recommended to ensure the wheel washing facility was operated at the construction site entrance and closely monitor the effectiveness of the wheel washing facility.

No further complaint was received and the complaint was closed.

• A complaint was referred by CEDD (ICC) regarding the fugitive dust impact at the slope of Shun Chi Court on 31 August 2012.

Fugitive dust emission was potentially generated from the works area at the slope of Shun Chi Court. The works area has been covered by tarpaulin sheet and frequent watering have been carried out to minimize fugitive emission generated.

According to the routine 1-hour TSP and 24-hour TSP monitoring data recorded at the nearest monitoring station ID 1A (roof of Kwun Tong Government Secondary School) on 28 August 2012, the measured 24-hour TSP level was found to be $79\mu g/m^3$. The measured 1-hour TSP levels on 28 August 2012 were found to be $80.2\mu g/m^3$; $78.5\mu g/m^3$ and $79.9\mu g/m^3$ respectively. All measured 1-hour TSP and 24-hour TSP level were below the Action and Limit Level.

Despite that the 1-hour and 24-hour TSP levels were below the Action and Limit level. The Contractor was recommended to apply regular water spray to the works area and closely monitor the status of tarpaulin sheet to minimize fugitive emission generated.

No further complaint was received and the complaint was closed.

Please refer to the monthly EM&A report (September 2012 Version 0) accordingly for the details of the captioned complaint.

 A complaint was sent to CSCE regarding the construction noise impact in Portion S1a on 15 October 2012 via email.

According to the noise monitoring data recorded on 8 and 19 October 2012 at the nearest monitoring station ID5 (Sau Mau Ping Catholic Primary School), the measured noise level in Leq (30-min) were 63.2dB(A) and 62.6dB(A) respectively, which were below the Limit Level.

As advised by the Contractor, no construction activities involving the use of Powered Mechanical Equipment (PME), e.g. rock breaking or rock drilling works, were conducted in the concerned area in October 2012. Construction noise was potentially contributed by rock breaking activities of other projects at works area in Portion D and E nearby.

Although the complaint was not considered as project related, the Contractor was recommended to stipulate the following noise mitigation measures in case any construction activities involving the use of PME is conducted in the concerned area: rock breaking works should be stopped at 6pm, the noise mitigation measures should be maintained and the effectiveness of noise mitigation measures deployed within works area should be reviewed onsite regularly in order to provide sufficient noise screening effect properly for the noise sensitive receivers.

No further complaint was received and the complaint was closed.

Please refer to the monthly EM&A report (October 2012 Version 0) accordingly for the details of the captioned complaint.

5.1.2 Table 6.1 summarized the complaint, summons and successful prosecution received in the reporting period.

Table 6.1 Summary of Environmental Complaints, Summons and Prosecutions

	Sep 12	Oct 12	Nov 12	Total
Complaint Logged	2	1	0	3
Summons Served	0	0	0	0
Successful Prosecution	0	0	0	0

5.1.3 Cumulative Statistics on Exceedances, Complaints, Notification of Summons and Successful Prosecutions recorded since the commencement of the Project are given in Appendix F.

6 COMMENTS, RECOMMENDATIONS AND CONCLUSIONS

6.1 Comments on Mitigation Measures

6.1.1 According to the environmental site inspections performed in the reporting quarter, the following comments are provided:

6.1.2 Air Quality Impact

- Conduct regular inspection of the working machineries within works area to avoid any dark smoke emission.
- Regular water spraying or equivalent measure should be provided to the access roads, exposed surfaces/slopes and dusty construction works areas to minimize the dust impacts to sensitive receivers nearby.
- Temporary exposed slopes/surfaces should be completely covered up with tarpaulin sheet or shotcreted or hydroseeded if no works is going to carry out on them.
- Proper shelter, in form of covering on the top and at the 3 sides of the cement mixing works station, should be provided prior to any cement mixing work was carrying out on-site.

6.1.3 Construction Noise Impact

■ Proper and effective noise mitigation measures (e.g. provision of noise barriers, absorptive material coverage on scaffolding and absorptive material wrappings to the breaking tips of the breakers) should be implemented at the breaking and drilling works areas to minimize the noise impacts to sensitive receivers nearby. The Contractor should conduct regular review on and maintain the noise screening measures provided within works area.

6.1.4 Water Quality Impact

■ No specific observation was identified in the reporting quarter. However, the Contractor should provide effective temporary drainage systems/channels and wastewater treatment systems and operate properly in works area to cater the surface run-off generated from works area and wheel washing facility. Surface run-off should be properly treated prior to discharge. Any untreated run-off should be avoided from overflowing to public drains. Temporary drainage systems/channels and wastewater treatment systems should be maintained and reviewed regularly and deposited silt and debris inside the temporary drainage channels/systems should be cleared regularly.

6.1.5 Chemical and Waste Management

- Any oil stains and oil mixture found within the works area should be cleared and disposed of them as chemical waste. Proper measures (e.g. provision of drip trays or temporarily with tarpaulin sheets) should be provided if works with potential oil leakage was carrying out. Regular inspection should be conducted at works area to avoid accumulation of chemical waste in works area
- All air compressor, chemical containers and oil drums placed within the works area should be stored with provision of drip trays in order to retain any oil and chemical leakage.

6.1.6 Landscape and Visual Impact

■ Proper tree protection measures (e.g. provision of netting to demarcate the protection zone) should be provided to existing trees to avoid accidental damage to them.

AECOM Asia Co. Ltd. 18 December 2012

6.2 Recommendations on EM&A Programme

- 6.2.1 The impact air quality and noise monitoring programme ensured that any environmental impact to the receivers would be readily detected and timely actions could be taken to rectify any non-compliance. Assessment and analysis of monitoring results collected demonstrated the environmental acceptability of the Project. The weekly site inspection ensured that all the environmental mitigation measures recommended in the EIA report were effectively implemented.
- 6.2.2 The EM&A programme effectively monitored the environmental impacts from the construction activities and no particular recommendation was advised for the improvement of the programme.

6.3 Conclusions

- 6.3.1 Air quality and noise monitoring and weekly site inspection were carried out from September 2012 to November 2012, in accordance with the EM&A Manual.
- 6.3.2 All 1-hour and 24-hour TSP monitoring results complied with the Action and Limit level at all monitoring locations in the reporting quarter.
- 6.3.3 As per Contractor's information, one (1) noise complaint was received in the reporting quarter. Hence, one (1) Action Level exceedance was noted in the reporting period and no Limit Level exceedance of noise were recorded in the reporting quarter.
- 6.3.4 Referring to the Contractor's information, two (2) air complaints, one (1) noise complaint and no notification of summons and successful prosecution were received in the reporting quarter.
- 6.3.5 Environmental site inspections were carried out 13 times in the reporting period. Recommendations on remedial actions were given to the Contractor for the deficiencies identified during the site audit.