


VSR 14 - View from Stanley Waterfront - Existing condition at the Development Site.




View displaying the 3D Model of the Wind Farm without Mitigation







View displaying the 3D Model of the wind farm with Mitigation at Day 1 Operation



View displaying the 3D Model of the wind farm with Mitigation at year 10 operation.

