

VP10 - FANLING GOLF COURSE - EXISTING SITE CONDITION




PHOTOMONTAGE WITHOUT MITIGATION MEASURES



PHOTOMONTAGE WITH MITIGATION MEASURES AT DAY 1



PHOTOMONTAGE WITH MITIGATION MEASURES AT YEAR 10



KEY PLAN

## NOTES:

- 1. ALL DIMENSIONS ARE IN MILLIMETRES UNLESS OTHERWISE STATED.
- 2. ALL LEVELS ARE IN METRES (M) AND RELATIVE TO HONG KONG PRINCIPAL DATUM (mPD).
- 3. FOR ILLUSTRATION ONLY. SUBJECT TO REVIEW.



AGREEMENT NO. CE 17/2021 (CE) TECHNICAL STUDY ON PARTIAL DEVELOPMENT OF FANLING GOLF COURSE SITE - FEASIBILITY STUDY

PHOTOMONTAGE OF VIEWING POINT 10

FIGURE 11.10.10			Rev.
Drawn	Date	Checked	Approved
CAD	NOV 2021	LW	EW
Scale		Status	
N.T.S.			-
C COPYRIGHT RESERVED			



土木工程拓展署
CIVIL ENGINEERING AND DEVELOPMENT
DEPARTMENT
址拓展處
NORTH DEVELOPMENT OFFICE