

VP5 - TAI LUNG EXPERIMENTAL FARM - EXISTING SITE CONDITION




PHOTOMONTAGE WITHOUT MITIGATION MEASURES



PHOTOMONTAGE WITH MITIGATION MEASURES AT DAY 1



PHOTOMONTAGE WITH MITIGATION MEASURES AT YEAR 10



KEY PLAN

## NOTES:

- 1. ALL DIMENSIONS ARE IN MILLIMETRES UNLESS OTHERWISE STATED.
- ALL LEVELS ARE IN METRES (M) AND RELATIVE TO HONG KONG PRINCIPAL DATUM (mPD).
- 3. FOR ILLUSTRATION ONLY. SUBJECT TO REVIEW.





AGREEMENT NO. CE 17/2021 (CE)
TECHNICAL STUDY ON PARTIAL DEVELOPMENT
OF FANLING GOLF COURSE SITE
- FEASIBILITY STUDY

PHOTOMONTAGE OF VIEWING POINT 5

Drawing no.	FIGURE 11.10	0.5	Rev.
Drawn	Date	Checked	Approved
CAD	NOV 2021	LW	EW
Scale	•	Status	•
N.T.S.			-

C COPYRIGHT RESERVED



土木工程拓展署
CIVIL ENGINEERING AND DEVELOPMENT
DEPARTMENT
北拓展處
NORTH DEVELOPMENT OFFICE