

VP-SK2 – EXISTING CONDITION



DAY 1 WITHOUT MITIGATION MEASURE



DAY 1 WITH MITIGATION MEASURE



10 YEARS WITH MITIGATION MEASURE

CM01	Tree Protection and Preservation	
CM02	Tree Transplantation	
CM03	Works Area and Temporary Works Areas	
CM04	Advance Implementation of Mitigation Planting	
CM05	5 Decorative Screen Hoarding	
CM06	O6 Control of night-time lighting	
OM01	Integrated Design Approach	
OM02	Roadside Planting	
OM03	Compensatory Planting Proposals	
OM04	Post-Planting Monitoring	
OM05	Greening Works on Slopes and associated Structure	
ОМ06	Design of Tunnel Portals and landscape treatment	
OM07	Design of an Elegant Bridge Structure and Approach Roads	
OM08	Provision of Visually Pleasing Aesthetic Treatment of Noise Mitigation Measures	
ОМ09	Provision of Green Roof	

## NOTE : REFER TO FIGURE 11.10.4 FOR VIEWPOINT LOCATION

В	REVISION	BS	06/23	
Α	FIRST ISSUE	BS	01/23	
Rev	Description	Ву	Date	

## **ARUP**

Agreement No. CE 13/2021 (HY) Route 11 (Section between Yuen Long and North Lantau) - Investigation.

## PHOTOMONTAGE OF VP-SK2 VEHICLE TRAVELLERS ON TUEN MUN ROAD

Drawing no.	Rev. B			
Drawn RY	Date 10/21	Checked IL	Approved SK	
Scale		Status PRE	Stotus PREL [M]NARY	

