


VP-SK14 – EXISTING CONDITION



DAY 1 WITHOUT MITIGATION MEASURE



DAY 1 WITH MITIGATION MEASURE



10 YEARS WITH MITIGATION MEASURE

CM01	Tree Protection and Preservation	
CM02	Tree Transplantation	
CM03	Works Area and Temporary Works Areas	
CM04	Advance Implementation of Mitigation Planting	
CM05	Decorative Screen Hoarding	
CM06	Control of night-time lighting	
OM01	Integrated Design Approach	
OM02	Roadside Planting	
OM03	Compensatory Planting Proposals	
OM04	Post-Planting Monitoring	
OM05	Greening Works on Slopes and associated Structure	
OM06	Design of Tunnel Portals and landscape treatment	
OM07	Design of an Elegant Bridge Structure and Approach Roads	
OM08	Provision of Visually Pleasing Aesthetic Treatment of Noise Mitigation Measures	
ОМ09	Provision of Green Roof	
_		

NOTE : REFER TO FIGURE 11.10.3 FOR VIEWPOINT LOCATION

c 8			
	FIRST ISSUE	BS	06/23
Rev	Description	Ву	Date

Consultant

ARUP

roject title

Agreement No. CE 13/2021 (HY) Route 11 (Section between Yuen Long and North Lantau) - Investigation.

Drawing title

PHOTOMONTAGE OF VP-SK14 TRAIL WALKERS ON TAI LAM CHUNG RESERVOIR SUBSIDIARY DAM AT SIU LAM ROAD

	FIGURE	11.10.22	A
Drawn	Date	Checked	Approved
RY	10/21	IL	SK
Scale		Status	LIMINARY

