


EXISTING CONDITION



DAY 1 WITHOUT MITIGATION MEASURES



DAY 1 WITH MITIGATION MEASURES



YEAR 10 WITH MITIGATION MEASURES

NOTES:
1. PLEASE REFER TO FIGURE 11.11.1 AND 11.11.2 FOR LOCATION OF VIEWING POINT.

ID No.	Construction Phase Mitigation Measures
CM01	Tree Protection and Preservation
CM02	Tree Transplantation
CM03	Works Area and Temporary Works Areas
CM04	Advance Implementation of Mitigation Planting
CM05	Decorative Screen Hoarding
CM06	Control of night-time lighting
OM01	Integrated Design Approach
OM02	Roadside Planting
OM03	Compensatory Planting Proposals
OM04	Post-Planting Monitoring
OM05	Treatment of Retaining Wall and Slopes
OM06	Design of Tunnel Portals
OM07	Reinstatement of disturbed Open Space

C	THIRD ISSUE	LFM	08/23
B	SECOND ISSUE	LFM	06/23
A	FIRST ISSUE	LFM	06/22
Rev	Description	By	Date

Consultant

ARUP

Project title
Agreement No. CE 65/2021(HY)
Tuen Mun Bypass - Investigation

Drawing title
PHOTOMONTAGE OF
VP-PP2 – WORKERS AT EMSD
TUEN MUN VEHICLE SERVICING
STATION AND DSD PILLAR
POINT STW

Drawing no. **FIGURE 11.13.2** Rev. **C**

Drawn	RY	Date	06/22	Checked	AW	Approved	SK
-------	----	------	-------	---------	----	----------	----

Scale	N. T. S.	Status	PRELIMINARY
-------	----------	--------	-------------

COPYRIGHT RESERVED

 路政署
HIGHWAYS DEPARTMENT