

EIA Study for SCL Protection Works at Causeway Bay Typhoon Shelter
 Tracer Modelling Results for Zinc under Dry Season
 Red: Exceedance in Zinc

JUNE 2010


Dry Season

Appendix 3.8-01

AECOM Asia Company Limited

60050763/GPP

Scn1PW-contaminant-a.ssn



EIA Study for SCL Protection Works at Causeway Bay Typhoon Shelter
 Tracer Modelling Results for Total PCBs under Dry Season
 Red: Exceedance in PCB

JUNE 2010


Dry Season

Appendix 3.8-02

AECOM Asia Company Limited

60050763/GPP

Scn1PW-contaminant-a.ssn



EIA Study for SCL Protection Works at Causeway Bay Typhoon Shelter
 Tracer Modelling Results for Total PAHs under Dry Season
 Red: Exceedance in PAH

JUNE 2010


Dry Season

Appendix 3.8-03

AECOM Asia Company Limited

60050763/GPP

Scn1PW-contaminant-a.ssn



EIA Study for SCL Protection Works at Causeway Bay Typhoon Shelter
 Tracer Modelling Results for Zinc under Wet Season
 Red: Exceedance in Zinc

JUNE 2010


Wet Season

Appendix 3.8-04

AECOM Asia Company Limited

60050763/GPP

Scn1PW-contaminant-a.ssn



EIA Study for SCL Protection Works at Causeway Bay Typhoon Shelter
 Tracer Modelling Results for Total PCBs under Wet Season
 Red: Exceedance in PCB

JUNE 2010


Wet Season

Appendix 3.8-05

AECOM Asia Company Limited

60050763/GPP

Scn1PW-contaminant-a.ssn



EIA Study for SCL Protection Works at Causeway Bay Typhoon Shelter
 Tracer Modelling Results for Total PAHs under Wet Season
 Red: Exceedance in PAH

JUNE 2010

Wet Season

Appendix 3.8-06

AECOM Asia Company Limited

60050763/GPP

Scn1PW-contaminant-a.ssn