

Sam Shing Templ

EXISTING CONDITION



DAY 1 WITHOUT MITIGATION MEASURES



DAY 1 WITH MITIGATION MEASURES



YEAR 10 WITH MITIGATION MEASURES

NOTES:

1. PLEASE REFER TO FIGURE 11.11.1 AND 11.11.2 FOR LOCATION OF VIEWING POINT.

В	REVISION	LFM	08/23
Α	FIRST ISSUE	LFM	04/23
Rev	Description	Ву	Date

ARUP

Agreement No. CE 65/2021(HY) Tuen Mun Bypass - Investigation

PHOTOMONTAGE OF VP-TM12 – VISITORS OF SAM SHING TEMPLE IN CASTLE PEAK ROAD – CASTLE PEAK BAY

Drowing	Rev. B					
Drown	RY	Date 06/22	Checked AW	Approved SK		
Scale N. T. S.		PREL IMINARY				

