

EIA Study for SCL Protection Works at Causeway Bay Typhoon Shelter
Average Surface SS Elevations, Spring-Neap Cycle

JUNE 2010


Dry Season

Appendix 3.4-01

AECOM Asia Company Limited

60050763/GPP

11D-PW2b-Scn1.ssn



EIA Study for SCL Protection Works at Causeway Bay Typhoon Shelter
Average Mid-Depth SS Elevations, Spring-Neap Cycle

JUNE 2010


Dry Season

Appendix 3.4-02

AECOM Asia Company Limited

60050763/GPP

11D-PW2b-Scn1.ssn



EIA Study for SCL Protection Works at Causeway Bay Typhoon Shelter
 Average Bottom SS Elevations, Spring-Neap Cycle

JUNE 2010


Dry Season

Appendix 3.4-03

AECOM Asia Company Limited

60050763/GPP

11D-PW2b-Scn1.ssn



EIA Study for SCL Protection Works at Causeway Bay Typhoon Shelter
Average Sedimentation Flux, Spring-Neap Cycle

JUNE 2010

Dry Season

Appendix 3.4-04

AECOM Asia Company Limited

60050763/GPP

11D-PW2b-Scn1.ssn