



VP4 (from bike lane adjacent to the planned Visitation Church): Existing Condition



Day 1 Operational Phase With Mitigation Measure



Day 1 Operational Phase Without Mitigation Measure



Year 10 Operational Phase With Mitigation Measure

LEGEND

Rev	Date	Descriptions	Check



HONG KONG INTERNATIONAL AIRPORT



Consultant's Signatures for Approval	Date
Design Supervisor	
Checkers	
Authorised Representative	

Key Plan

PHOTOMONTAGE VP4

Drawing No.

FIGURE 10.11d

riginator Location Discipline Typo Dwg Sequence No.

Use Design Scale Rev