Appendix 7.2 - Acquisition of Information from Government Departments



AECOM +852 3922 9000 tel 12/F Grand Central Plaza, Tower 2 +852 3922 9797 fax 138 Shatin Rural Committee Road Shatin, Hong Kong 季滋新男沙田鄉富會路 138 聽

香港新界沙田鄉事會路 138 號 新城市中央廣場第 2 座 12 樓 www.aecom.com

Our Ref: DTPL:PKHF:wcsw:60607462/04.07-2021013153L

3 September 2021

By Post and Fax (F: 2411 3073)

Environmental Protection Department Regional Office (West) 8/F, Tsuen Wan Government Offices, 38 Sai Lau Kok Road, Tsuen Wan, New Territories

Dear Sir/Madam.

Agreement No. CE 61/2018 (HY)
Widening of Tsuen Wan Road, Extension of Existing Vehicular Bridge at Texaco Road and the Associated Junction Improvement Works – Investigation

Request for Information of Chemical Waste Producer and Chemical Spillage Accident

AECOM Asia Co. Ltd. has been commissioned by Highways Department as the Consultant to undertake land contamination assessment for the captioned Project. The Project Boundary is indicated in the figure enclosed.

As part of the land contamination assessment and following the *Practice Guide for Investigation and Remediation of Contamination Land* issued by EPD, we have to collect historical information regarding the past and present activities within the Project Boundary. In order to facilitate our assessment, we would like to request for the following information regarding the captioned Project Boundary:

- Current and past (as early as the records are available) registered Chemical Waste Producer(s)
 within the Project Boundary (preferably with the registration date, status (moved out or active),
 nature and quantity of the chemical waste); and
- 2. Reported accidents of spillage / leakage of chemicals within the Project Boundary.

We would be grateful if you could provide us the abovementioned information on or before 17 September 2021. Should you have any query, please feel free to contact our Ms. Chloe Ng at 3922 9305.

Yours faithfully, For and on behalf of AECOM Asia Co. Ltd.

Derek Tai
Associate Director
Land Supply / Municipal, Hong Kong

Encl.

本署檔號 EP747/M1/01 (Part 5)

Our Ref.: 來的檔號 Your Ref.;

证 舗 2417.6121

Tel. No.:

圖文例真 2411 3073

Fax No.:

電子郵件 E-Mail:

利 加 Homepage: http://www.epd.gov.hk/

Environmental Protection Department Environmental Compliance Division Regional Office (West)

8/F., Tsuen Wan Government Offices, 38 Sai Lau Kok Road, Tsuen Wan, N.T.



環境保護署環保法規管理科區域辦事處(西)新界全灣西級角路 38 號

(Fax. No. 3922 9797) 17 Sep 2021

Dear Derek TAI,

Agreement No. CE 61/2018 (HY)
Widening of Tsuen Wan Road, Extension of Existing Vehicular
Bridge at Texaco Road and the Associated Junction
Improvement Works – Investigation

Request for information of Chemical Waste Producer and Chemical Spillage Accident

I refer to your letter (your ref.: DTPL:PKHF:wcsw:60607462/04.07-2021013153L) dated 3 Sep 2021 for the captioned issue.

There is no chemical spillage / leakage record within the proposed project boundary in Kwai Tsing district in this office. For record of Chemical Waste Producers, please contact our Chemical Waste and WEEE (Licensing and Control Support) Section, Mr. Andy Ma, at 2835 1357 for the record searching.

Should you have any enquiries, please contact the undersigned at 2417 6121.

Yours faithfully,

(YE Yin, Justin)

for Director of Environmental Protection

wcsw:

本署檔號
Our Ref.: () EP/RW/TW/General
來函檔號

DTPL:PKHF:

60607462/04.07-2021013153L

Environmental Protection Department Regional Office (West)

> 8/F., Tsuen Wan Government Offices, 38 Sai Lau Kok Road, Tsuen Wan N.T.



電 話

Your

Tel. No.: 2417 6087

國文傳真

2411 3073

Fax No.: 電子郵件 E-Mail:

址

Homepage: http://www.epd.gov.hk

20 Sep 2021

By mail and fax:

3922 9797

AECOM Asia Co. Ltd, 12/F, Grand Central Plaza, Tower 2, 138 Shatin Rural Committee Road, Shatin, N.T. (Attn: Derek TAI, Associate Director of Land Supply/Municipal)


Dear Derek TAI,

Widening of Tsuen Wan Road, Extension of Existing Vehicular Bridge at Texaco Road and the Associated Junction Improvement Works – Investigation [Agreement No. CE 61/2018 (HY)]

Enquiry for Chemical Waste Producer and Chemical Spillage Accident Record

I referred to your incoming letter of the above subject received by this office on 10 Sep 2021.

There was no chemical waste spillage accident record of the subject site in Tsuen Wan area (as marked in blue in the below drawing). I also noted that you were enquiring the Kwai Tsing record (i.e. the rest of your project area) from the Kwai Tsing Section of Regional Office (West), EPD.



For the record of Chemical Waste Producers of the subject Site, please contact the Chemical Waste and WEEE (Licensing and Control Support) Section, Mr. Andy Ma, at 2835 1357 for the record searching.

Should you have any enquiries, please contact the undersigned at 2417 6087.

Yours faithfully,

(LAM Ka-ho) for Director of Environmental Protection



AECOM +852 3922 9000 tel 12/F Grand Central Plaza, Tower 2 +852 3922 9797 fax

138 Shatin Rural Committee Road Shatin, Hong Kong 香港新界沙田鄉事會路 138 號 新城市中央廣場第 2 座 12 樓 www.aecom.com

Our Ref: DTPL:PKHF:wcsw:60607462/04.08-2021013154L

3 September 2021

By Post and Fax (F: 2367 3631)

Fire Services Department Licensing and Certification Command 5/F, South Wing, Fire Services HQ Building, 1 Hong Chong Road, Tsim Sha Tsui East, Kowloon

Dear Sir/Madam.

Agreement No. CE 61/2018 (HY)
Widening of Tsuen Wan Road, Extension of Existing Vehicular Bridge at Texaco Road and the Associated Junction Improvement Works – Investigation

Request for Information about Dangerous Goods Store and Incident Records

AECOM Asia Co. Ltd. has been commissioned by Highways Department as the Consultant to undertake land contamination assessment for the captioned Project. The Project Boundary is indicated in the figure enclosed.

As part of the land contamination assessment and following the *Practice Guide for Investigation and Remediation of Contamination Land* issued by EPD, we have to collect historical information regarding the past and present activities within the Project Boundary. In order to facilitate our assessment, we would like to request for the following information regarding the captioned Project Boundary:

- Records of current and past (as early as the records are available) registration of Dangerous Goods storage (with type of dangerous goods, storage method, quantity, license no., date of issue and storage location) within the Project Boundary;
- 2. Any records of reported accidents of spillage / leakage of dangerous goods stored within the Project Boundary; and
- 3. Any records of fire incidents within the Project Boundary.

We would be grateful if you could provide us the abovementioned information on or before 17 September 2021. Should you have any query, please feel free to contact our Ms. Chloe Ng at 3922 9305.


Yours faithfully, For and on behalf of AECOM Asia Co. Ltd.

Derek Tai Associate Director Land Supply / Municipal, Hong Kong

Encl.

CC

Widening of Tsuen Wan Road and the associated junction improvement works



AECOM

AECOM +852 3922 9000 tel 12/F Grand Central Plaza, Tower 2 +852 3922 9797 fax

138 Shatin Rural Committee Road Shatin, Hong Kong 香港新界沙田鄉事會路 138 號 新城市中央廣場第 2 座 12 樓

www.aecom.com

Our Ref: DTPL:PKHF:wcsw:60607462/04.08- 2020006859L

30 June 2020

By Post & Fax (2739 5879)

Fire Services Department
Fire Services Headquarters Command
Management Group (MG)
9/F, Fire Services Headquarters Building
1, Hong Chong Road, Tsim Sha Tsui East
Kowloon

Attn.: Mr. W.C. KONG [Asst. Div. Offr. (Management Group) 1]

Dear Sir/Madam,

Agreement No. CE 61/2018 (HY)
Widening of Tsuen Wan Road, Extension of Existing Vehicular Bridge at Texaco Road and the Associated Junction Improvement Works – Investigation

Request for Information regarding Dangerous Goods Store and Incidents Records

We refer to your letter (112) in FSD GR 6-5/4 R Pt. 27 dated 23 June 2020.

AECOM Asia Co. Ltd has been commissioned by Highways Department as the Consultant to undertake land contamination assessment for the captioned project. A copy of a self-explanatory memo from HyD ref.: (JPDU) in HYD MWO 11/1/877TH/7/1 dated in 30 May 2019 is enclosed herewith for your reference.

As a part of the land contamination assessment and following the <u>Practice Guide for Investigation and Remediation of Contaminated Land (EPD, 2011)</u>, we have to collect historical information regarding the past and present activities within the Project Boundary. The Project Boundary, concerned building names and street names are indicated in the figure enclosed. A list of affected land lots is also enclosed for your reference. In order to facilitate our assessment, we would like to request for the following information regarding the captioned Project Boundary:

- 1. Records of current and past (as early as the records are available) registration of Dangerous Goods storage (with type of dangerous goods, storage method, quantity, licence no., date of issue and storage location) within the Project Boundary;
- Any records of reported accidents of spillage/leakage of dangerous goods stored within the Project Boundary; and
- 3. Any records of fire incidents within the Project Boundary.

Please feel free to contact our Ms. Chloe Ng at 3922 9305 / Mr. Robert Yuen at 3922 9439 should you have any queries.

Thank you very much for your kind assistance.

Yours faithfully, For and on behalf of AECOM Asia Co. Ltd.

Derek Tai

Associate Director

Land Supply / Municipal, Hong Kong

Encl.

CC

HyD/MW/CE (Attn.: Ms. Julie O)

(Fax: 2714 5289)

<u>M</u>	EMO
From CE5/MW, MWPMO, HyD	To Distribution
Ref. (JPDU) in <u>HYD MWO 11/1/877TH/7/1</u>	(Attn.:
Tel. No. 2762 3622	Your Ref.
Fax. No. 2714 5289	Dated Fax No.
Date 30 May 2019	Total Pages 2 + Encl.

Agreement No. CE 61/2018 (HY)
Widening of Tsuen Wan Road,
extension of existing vehicular bridge at Texaco Road and
the associated junction improvement works

— Investigation

Appointment of Consultant

I write to inform that AECOM Asia Company Limited (AECOM) has been appointed as the Consultant to undertake the captioned Assignment. The Assignment commenced on 23 May 2019 for completion in November 2021. A layout plan showing the improvement works to be investigated under the Assignment is enclosed for your reference.

- 2. The Assignment involves evaluation of the Initial Scheme and alternative schemes developed, formulation of the Preferred Scheme, preliminary design of the Preferred Scheme, various impact assessments, site investigation works, public consultation, gazettal of the Preferred Scheme, etc.
- 3. During the course of the Assignment, AECOM may contact you for information, assistance or other matters relating to the Assignment. I would like to seek your cooperation and assistance to AECOM in carrying out their services for the Assignment.
- 4. The Project Manager of AECOM for the Assignment is Mr. Derek Tai. The contact details are as follows:

Tel. : 3922 8401 Fax : 3922 9797

E-mail : derek.tai@aecom.com

Address : 8/F Grand Central Plaza, Tower 2, 138 Shatin Rural Committee

Road, Shatin, Hong Kong

5. Should you require any further information on the above Assignment, please contact my Senior Engineer, Mr. Clement POON at 2762 3539 or my Engineer, Mr. Wilson HO at 2762 3641.

(Ms. Julie O)

Chief Engineer 5/ Major Works
Major Works Project Management Office
Highways Department


Distribution – w/e		
DPO/TW&WK, PlanD	(Attn: Mr. TSANG Ho Cheung, Robert)	2412 5435
DLO/TW&KT, LandsD	(Attn: Mr. CHAU King Man)	2415 0703
CE/TS&S, TD	(Attn: Mr. YUEN Ting Fung, Jacky)	2381 3799
CTE/NTW, TD	(Attn: Mr. LI Hok Lai, Matthew)	2381 3799
CTO/NTSW, TD	(Attn: Mr. LAU Wing Hang, Will)	2381 3799
CE/SSD, TD	(Attn: Mr.FUNG Siu Cheuk, Peter)	2824 2741
EO/Driving Op, TD	(Attn: Mr. CHAN Kwok Hung, Kevin)	2711 6799
CE/LWD, CEO (Port &	(Attn: Mr. CHOI Wing Hing)	2714 0695
Land), CEDD	· · · · · · · · · · · · · · · · · · ·	2714 0075
CE/W2, WDO, CEDD	(Attn: Mr. TSANG Lap Kei, Freddie)	2412 0358
CE/Fill Mgt, CEDD	(Attn: Ms. WONG Hoi Shan)	2714 0113
CE/SD(Works), CEDD	(Attn: Ms. CHIU Kwan Kiu, Natalie)	2714 0103
GE/MW13, GEO, CEDD	(Attn: Ms. SIU Kar Kei)	2194 0165
PWCL, GEO, CEDD	(Attn: Mr. KAM Wai Tsun)	2795 2545
CPM 303, ArchSD	(Attn: Mr.LEUNG Man Chung)	2537 3713
EO(Planning)7, LCSD	(Attn: Ms. LO Wai Yin, Phoenix)	2695 3886
EPO(SA)23, EPD	(Attn: Ms. HO Tsz Yan, Kathy)	2591 0558
RMO(Traffic NTS HQ),	(Attn: Mr. LEUNG Chun Sing)	2200 4662
HKPF	(2200 4002
ADO(Planning Group)4, FSD	(Attn: Mr. CHAN Ming Chung)	2739 8775
CE/Mainland South, DSD	(Attn: Ms. LO Sze Yan)	2771 9640
E/NTW (Distribution 1), WSD	(Attn: Mr. SZETO Wai Tun)	2789 4680
DEHS(TW), FEHD	(Attn: Mr. CHOI Wai Wing)	2614 4392
SEO(Planning)6, FEHD	(Attn: Mr. TO Chi Wah, Eddie)	3101 0450
DO/TW, HAD	(Attn: Mr. CHOW Chun Hun, Gary)	2412 0244
DO/KT, HAD	(Attn: Ms. CHAN Yuk Na, Yuki)	2489 1083
CCE/D&C Div, HD	(Attn: Ms. CHAN Pui Man, Iris)	2628 9060
TS, EMSD	(Attn: Mr. WONG King Wai)	2882 5132
		2002 0102
<u>Internal – w/e</u>		
CE3/MW	(Attn: Mr. CHAN Chi Ming)	2714 5198
CHE/B&S	(Attn: Mr. CHEUNG Chi Wa)	2714 5219
CHE/Works	(Attn: Mr. CHAN Sze Ho)	3188 3418
CE/RD2-2	(Attn: Ms. LAM Hoi Ching, Jessica)	2761 1508
CE/Lighting	(Attn: Mr. LAU Yan Heng)	2310 8489
CHE/NTW	(Attn: Mr. WU Fan)	2714 5228
CLA/LD	(Attn: Mr. CHONG King Pan, Derek)	2310 8438
LS/MW	(Attn: Mr. TSE Calvin)	2394 5696
SE/Planning	(Attn: Mr. LAU Wai Leung)	2714 5216
c.c. – w/o AECOM Asia Company Limited	(Attn: Mr. Derek Tai)	3922 9797

Agreement No. CE 61/2018 (HY)

Widening of Tsuen Wan Road, extension of existing vehicular bridge at Texaco Road and the associated junction improvement works – Investigation

Affected Land Lots	Locations
	Kwai Shun Street Refuse Collection Point,
GLA-TW 199	Kwai Shun Street Playground, Kwai Shun
	Street Cooked Food Market, Kwai Shun
	Street Public Toilet
GLA-TW 278 (VO:NT535)	Hoi Shing Garden
GLA-TW 341	Tsuen Wan Park
GLA-TW 448	Tsuen Wan Park
GLA-TW 502	Hoi Hing Road Refuse Collection Point
GLA-TTW 876	
GLA-TTW 878	
GLA-TTW 695	Tsuen Wan Driving Test Centre
GLA-TKT 1704	Kwai Tsing Park
TWTL 307	Clague Garden Estate
TWTL 336	Tsuen Wan South Substation
VO: EX-NT-4b	
STT1521TW	
STT1524TW	
STT1481TW	
STT1514TW	
STT1517TW	
STT1518TW	
STT3750K&T	

Roads	
HOI ON ROAD	
HOI HING ROAD	
TSUEN WAN ROAD	
TEXACO ROAD	
TSING TSUEN ROAD	
TSUEN TSING INTERCHANGE	
KWAI TSING ROAD	
TAI HO ROAD	
TAI CHUNG ROAD	
WING SHUN STREET	
WING KEI ROAD	
KWAI HEI STREET	



消 防 處 智港九點尖沙咀東部最莊超1號 消防銀部大廈



FIRE SERVICES DEPARTMENT
FIRE SERVICES HEADQUARTERS
BUILDING,
No.1 Hong Chong Road,

Tsim Sha Taui East, Kowloon.
Hong Kong.

本處橋號 OUR REF. : (43) in FSD GR 6-5/4 R Pt. 28

來的檔號 YOUR REF. : DTPL:PKHF:wcsw:60607462/04.08-2020006433L

電子郵件 E-mail : hkfsdenq@hkfsd.gov.hk

國文傳真 FAX NO. : 2739 5879 電 話 TEL NO. : 2733 7741

20 August 2020

AECOM Asia Co. Ltd. 12/F Grand Central Plaza, Tower 2, 138 Shatin Rural Committee Road, Shatin, Hong Kong.

(Attn: Mr. Derek TAI, Associate Director)

By fax (3922 9797) only

Dear Mr. TAI,

Agreement No. CE 61/2018 (HY)

Widening of Tsuen Wan Road Extension of Existing Vehicular Bridge at Texaco Road and the Associated Junction Improvement Works - Investigation Request for Information of Dangerous Goods & Incident Records

I refer to your letter of 30.6.2020 regarding the captioned subject and reply below in response to your questions.

- 1. Licensed dangerous goods are stored at the captioned address. Please refer to Appendix A for details.
- Three incident records were found at the subject location.
 Please refer to <u>Appendix B</u> for details.

If you have further questions, please feel free to contact the undersigned.

Yours sincerely,

(KONG Wai-chung)
for Director of Fire Services

Appendix A

Agreement No. CE 61/2018 (HY) Widening of Tsuen Wan Road Extension of Existing Vehicular Bridge at Texaco Road and the Associated Junction Improvement Works - Investigation Request for Information of Dangerous Goods & Incident Records

<u>Item</u>	Type of DG	Store Location	
1.	Cat. 2	6/F, Tsuen Wan Industrial Centre, Texaco Road, Tsuen Wan	
2.	Cat. 5	TW5 Bayside Property Development Tsuen Wan Town, Lot No. 401	
3.	Cat. 2	6/F & 7/F, 35 Wing Kei Road, Kwai Chung	

26/08/2020 11:31 No.: R619 L1 P.002/003

Appendix B

Agreement No. CE 61/2018 (HY) Widening of Tsuen Wan Road Extension of Existing Vehicular Bridge at Texaco Road and the Associated Junction Improvement Works - Investigation Request for Information of Dangerous Goods & Incident Records

No.	Date	Type of Incident	Address	
1.	16.2.2017	Rubbish Fire	Roadside near Lamp Post No. FC0347 of Tsuen Wan Road	
2.	27.5.2017	No.1 Fire Alarm	Flower bed underneath Tsuen Wan Road near Lamp Post No. FC0475	
3.	2.11.2019	No.1 Fire Alarm	Near Lamp Post FC0358 of Tsuen Wan Road	

消防處 香港九龍尖沙咀東部康莊道1號 消防處總部大廈



FIRE SERVICES DEPARTMENT FIRE SERVICES HEADQUARTERS BUILDING,

No.1 Hong Chong Road, Tsim Sha Tsui East, Kowloon, Hong Kong.

本處檔號 OUR REF.

(78) in FSD GR 6-5/4 R Pt. 36

來函檔號 YOUR REF. :

DTPL:PKHF:wcsw:60607462/04.08-2021013154L

電子郵件 E-mail

7

hkfsdeng@hkfsd.gov.hk

圖文傳真 FAX NO.

2739 5879

電 話 TEL NO.

2733 7741

5 October 2021

AECOM Asia Co. Ltd. 12/F Grand Central Plaza, Tower 2, 138 Shatin Rural Committee Road, Shatin, Hong Kong.

(Attn: Mr. Derek TAI, Associate Director)

Dear Mr. TAI,

Agreement No. CE 61/2018 (HY)

Widening of Tsuen Wan Road Extension of Existing Vehicular Bridge at Texaco Road and the Associated Junction Improvement Works - Investigation Request for Information of Dangerous Goods & Incident Records

I refer to your letters of 3.9.2021 and 27.9.2021 regarding the captioned subject and reply below in response to your questions.

- 1. Licensed dangerous goods are stored at the captioned address. Please refer to **Appendix A** for details.
- 2. Sixteen incident records were found at the subject location. Please refer to **Appendix B** for details.

If you have further questions, please feel free to contact the undersigned.

Yours sincerely,

(NG Wing-chit)
for Director of Fire Services

Agreement No. CE 61/2018 (HY)

Widening of Tsuen Wan Road Extension of Existing Vehicular Bridge at Texaco Road and the Associated Junction Improvement Works – Investigation Request for Information of Dangerous Goods & Incident Records

<u>Item</u>	Cat.	Type of DG	Quantity	Store Location	
1.	2	FM 200	2 x 1000kg	Tsuen Wan Industrial Centre,	
2.	2	Nitrogen	6 x 68kg	Texaco Road, Tsuen Wan	
3.	5	Diesel Oils	1100 litre		
4.	5	Diesel Oils	1100 litre	TW5 Bayside Property	
5.	5	Diesel Oils	490 litre	Development at Tsuen Wan Town Lot. No.401	
6.	5	Diesel Oils	490 litre		
7.	2	Freon 22	8000 kg	No.35 Wing Kei Road	
8.	5	Diesel	1500 litre	No. 252 Texaco Road	
9.	5	Diesel	1500 litre	No. 252 Texaco Road	
10.	3	Potassium Hydroxide	125 kg		
11.	3	Sodium Hydroxide	450 kg		
12.	3	Sulphuric acid 98% (CP)	300 litre		
13.	3	Sulphuric acid 98% (AR)	50 litre		
14.	3	Hydrochloric acid (31%)	400 litre	Tsuen Wan Industrial Centre, 220-248 Texaco Road, Tsuen Wan	
15.	4	Potassium Cyanide	220 kg	220 210 Tenaco Roda, Tsuch Wa	
16.	4	Copper Cyanide	80 kg		
17.	7	Hydrogen Peroxide (50%)	200 litre		
18.	7	Sodium Chlorate 40%-50%	400 litre		

Agreement No. CE 61/2018 (HY) Widening of Tsuen Wan Road Extension of Existing Vehicular Bridge at Texaco Road and the Associated Junction Improvement Works - Investigation Request for Information of Dangerous Goods & Incident Records

No.	Date	Type of Incident	Address / Lamp Post No.
1.	26.10.2018	No. 1 Alarm	LP FC4667 Kwai Hei Street
2.	27.10.2018	Rubbish Fire	LP FA9721 Near Kwai Fuk Road
3.	1.3.2019	Rubbish Fire	LP FC4667 Near Kwai Hei Street
4.	2.11.2019	No. 1 Alarm	LP FC4667 Near Tsuen Wan Road
5.	26.12.2019	Late Call	LP FC0557 Near Hing Fong Road
6.	12.2.2020	Rubbish Fire	LP GC1230 Near Kwai Hei Street
7.	5.6.2020	Rubbish Fire	LP FC0478 Near Tsuen Wan Road
8.	20.6.2020	Vehicle Fire	93 Kwai Fuk Road, Citic Telecom Tower
9.	21.7.2020	Rubbish Fire	LP BC2637 Junction of Hing Fong Road and Tsuen Wan Road
10.	2.12.2020	Vehicle Fire	LP FC1383 Roadside Container Port Road
11.	18.12.2020	Vegetation Fire	LP FC0450 Chun Shing Factory Estate
12.	29.12.2020	Vegetation Fire	LP FC0440 Near Tsing Tsuen Road
13.	10.4.2021	Vegetation Fire	LP FC5247 Near Tsing Tsuen Road
14.	8.5.2021	Vegetation Fire	LP FA5301 Near Tsing Tsuen Road
15.	12.5.2021	Rubbish Fire	LP FA5301 Near Tsing Tsuen Road
16.	30.5.2021	Vehicle Fire	LP W4953 Near Tsuen Tsing Interchange

Au, Kin

From: ado_mg_1@hkfsd.gov.hk

Sent: Monday, November 15, 2021 6:51 PM

To: Au, Kin

Cc: oe_mg_6@hkfsd.gov.hk

Subject: [EXTERNAL] *Restricted: Re: Agreement No. CE 61/2018 (HY)- Further enquires

about Dangerous Goods Store and Incidents Records

Dear Mr. AU,

Record had been checked and below please find the supplementary information for your reference:

<u>Item</u>	Store Location	
1. & 2.	(6/F) Tsuen Wan Industrial Centre, Texaco Road, Tsuen Wan	Cat. 2
7.	(6/F & 7/F) No. 35 Wing Kei Road, Kwai Chung	Cat. 2
10 18.	(4/F) Tsuen Wan Industrial Centre, 220-248 Texaco Road, Tsuen Wan	Cat .3, 4 and 7

Please also note that the Lamp Post number was checked and should be FA5247.

Sorry for any inconvenience caused.

Regards,

(NG Wing-chit)
Assistant Divisional Officer
(Management Group)1
Fire Services Department

Office: 2733 7741 Fax: 2739 5879

From: "Au, Kin" <kin.au@aecom.com>

To: "ado_mg_1@hkfsd.gov.hk" <ado_mg_1@hkfsd.gov.hk>

Cc: "Tso, Shiu Heng Lawrence" , "Leung, Leslie" , "Leung, Leslie" , "Leung, Leslie" , "Leung, Leung@aecom.com , "Leung, Leung@aecom.com , "Leung, Leung@aecom.com , "Leung@aecom.com <a href=

Date: 15/11/2021 10:57

Subject: Agreement No. CE 61/2018 (HY)- Further enquires about Dangerous Goods Store and Incidents Records

Dear Mr Ng,

I refer to your letters dated 20 August 2020 (ref.: (43) in FSD GR 6-5/4 R Pt.36), and 5 October 2021 (ref.: (78) in FSD GR 6-5/4 R Pt.36) regarding our captioned information request. Regarding to the DG information (Appendix A), may I confirm if the store location of Item 1,2,7,10-18 located on upper floors (i.e. 6/F and/or 7/F as mentioned in the 2020's reply)? We would like to have a more precise DG location in order to evaluate if there are any land contamination issue.

Summary of Dangerous Goods License information (2021)

<u>Item</u>	Store Location	Type of DG
1. & 2.	Tsuen Wan Industrial Centre, Texaco Road, Tsuen Wan	Cat. 2
7.	No. 35 Wing Kei Road, Kwai Chung	Cat. 2
10 18.	Tsuen Wan Industrial Centre, 220-248 Texaco Road, Tsuen Wan	Cat .3, 4 and 7

Regarding to the incident record, it is noted that the lamp post No. of incident No. 13 is not an existing lamppost (not found in GeoInfo Map), could it be a typo (i.e FA5247)?

Summary of Incident Records (2021)

No.	Address / Lamp Post No.	Date	Types of Incident
13.	LP FC5247 near Tsing Tsuen Road	10 April 2021	Vegetation Fire

Attached the letters for your reference.

Should you have any queries, please do not hesitate to contact our Mr. Kin Au at 3922 9507. Thank you very much for your kind assistance.

Regards,

Kin Au

Graduate Environmental Consultant, Environment, Hong Kong D +852 3922 9507 kin.au@aecom.com

AECOM aecom.com

Delivering a better world LinkedIn | Twitter | Facebook | Instagram