

Slope Number	Slope Type	Location	Maintenance Party	Maximum PPV (mm/s)	Maximum Shear Displacement (mm)
10NE-A/C 106	Cut Slope	Adjoining drainage channel at To Kau Wan	DSD	22.5	0.00
10NE-A/C 107	Cut Slope	300M EAST OF THE TOLL GATE OF NORTH LANTAU HIGHWAY, LANTAU	HyD	14.6	0.00
10NE-A/C 108	Cut Slope	500M EAST OF THE TOLL GATE OF NORTH LANTAU HIGHWAY, LANTAU	HyD	19.2	0.00
10NE-A/C 109	Cut Slope	MTRC Airport Railway Rectifier Transformer Room, North Lantau Highway, Lantau	HyD	9.8	0.00
10NE-A/C 110	Cut Slope	500M EAST OF THE TOLL GATE OF NORTH LANTAU HIGHWAY, LANTAU	HyD	99.7	0.02
10NE-A/C 111	Cut Slope	600M EAST OF THE TOLL GATE OF NORTH LANTAU HIGHWAY, LANTAU	HyD	112.6	0.05
10NE-A/C 112	Cut Slope	Reclamation NW of Tsing Ma Bridge Pier, Lantau, TW	Lands D	12.4	0.00
10NE-A/C 113	Cut Slope	Ng Kwu Leng, Lantau	Lands D	101.3	0.02
10NE-A/C 114	Cut Slope	Ng Kwu Leng, Lantau.	Lands D	119.5	0.09
10NE-A/C 116	Cut Slope	350M EAST OF THE TOLL GATE OF NORTH LANTAU HIGHWAY, LANTAU	HyD	16.8	0.00
10NE-A/C 117	Cut Slope	400M EAST OF THE TOLL GATE OF NORTH LANTAU HIGHWAY, LANTAU	HyD	25.6	0.00
10NE-A/C 118	Cut Slope	400M EAST OF THE TOLL GATE OF NORTH LANTAU HIGHWAY, LANTAU	HyD	22.7	0.00
10NE-A/C 119	Cut Slope	600M EAST OF THE TOLL GATE OF NORTH LANTAU HIGHWAY, LANTAU	HyD	14.0	0.00
10NE-A/C 120	Cut Slope	Cheung Tung Road, Island	Lands D	9.5	0.00
10NE-A/C 121	Cut Slope	Reclamation NW of Tsing Ma Bridge approach to Lantau, TW	CKWL3	6.3	0.00
10NE-A/C 122	Cut Slope	San Po Tsui, Lantau, TW	Lands D	3.4	0.00
10NE-A/C 124	Cut Slope	BELOW THE ENTRANCE OF KAP SHUI MUN BRIDGE, LANTAU	HyD	8.6	0.00
10NE-A/C 125	Cut Slope	BELOW THE NORTH LANTAU HIGHWAY, NEAR THE ENTRANCE OF KAP SHUI MUN BRIDGE, LANTAU	HyD	6.4	0.00
10NE-A/C 126	Cut Slope	ADJACENT TO TSING MA BRIDGE PIER, LANTAU, TSUEN WAN	HyD	5.1	0.00
10NE-A/C 127	Cut Slope	ADJACENT TO TSING MA BRIDGE PIER, LANTAU, TSUEN WAN	HyD	4.8	0.00
10NE-A/C 128	Cut Slope	UNDER THE NORTH LANTAU HIGHWAY, NEAR KAP SHUI MUN BRIDGE, LANTAU	HyD	5.6	0.00
10NE-A/C 129	Cut Slope	ADJACENT TO TSING MA BRIDGE PIER, LANTAU, TSUEN WAN	HyD	6.6	0.00
10NE-A/C 130	Cut Slope	ADJACENT TO TSING MA BRIDGE PIER, LANTAU, TSUEN WAN	HyD	5.5	0.00
10NE-A/C 131	Cut Slope	ADJACENT TO ACCESS ROAD, NORTH OF TSING MA BRIDGE PIER, LANTAU	HyD	4.8	0.00
10NE-A/C 132	Cut Slope	ADJACENT TO ACCESS ROAD, NORTH OF TSING MA BRIDGE PIER, LANTAU, TSUEN WAN.	HyD	5.2	0.00
10NE-A/C 140	Cut Slope	TSING MA CONTROL AREA (TMCA) - KAP SHUI MUN BRIDGE	HyD	6.1	0.00
10NE-A/C 158	Cut Slope	WITHIN MTRL2RP, TMC	HyD, MTRCL	11.9	0.00
10NE-A/C 163	Cut Slope	Below the North Lantau Highway, near the main entrance of Kap Shui Mun Bridge, Lantau.	HyD, Lands D	7.0	0.00
10NE-A/F 14	Fill Slope	260M EAST OF THE TOLL GATE OF NORTH LANTAU HIGHWAY, LANTAU	HyD	9.4	0.00
10NE-A/F 17	Fill Slope	300M East Of The Toll Gate Of North Lantau Highway, Lantau	Lands D	77.4	0.00
10NE-A/F 18	Fill Slope	300m East Of The Toll Gate Of North Lantau Highway, Lantau	Lands D	100.3	0.02
10NE-A/F 19	Fill Slope	ENTRANCE OF THE TUNNEL OF KAP SHUI MUN BRIDGE, LANTAU	HyD	13.0	0.00
10NE-A/F 21	Fill Slope	ACCESS ROAD TO QUAY ROAD UNDERNEATH NORTH LANTAU EXPRESS WAY, LANTAU	HyD	3.9	0.00
10NE-A/F 22	Fill Slope	BELOW THE NORTH LANTAU HIGHWAY, NEAR THE ENTRANCE OF KAP SHUI MUN BRIDGE, LANTAU	HyD	7.3	0.00
10NE-A/F 47	Fill Slope	Lantau Toll Plaza, Tsing Ma Control Area	HyD	20.3	0.00
10NE-A/FR 23	Fill Slope	ADJACENT TO ESS UNDER LANTAU SIDE OF TSING MA BRIDGE, LANTAU, TSUEN WAN.	HyD	6.3	0.00
10NE-A/R 6	Retaining Wall	Adjoining drainage channel to the E & N of DD362 Lot 8	DSD	14.3	0.00
10NE-A/R 7	Retaining Wall	Tsuen Wan	DSD	20.6	0.00
10NE-A/R 9	Retaining Wall	BELOW THE NORTH LANTAU HIGHWAY, NEAR THE ENTRANCE OF KAP SHUI MUN BRIDGE, LANTAU	HyD	6.7	0.00
10NE-A/R 10	Retaining Wall	At the Entrance of Kap Shui Mun Bridge, Lantau	HyD	13.6	0.00
10NE-A/R 11	Retaining Wall	West of Tsing Ma Bridge on West-Bound Carriageway Lantau, Tseun Wan	HyD	10.9	0.00
6NW-C/C 200	Cut Slope	Lam Tei Quarry, Tuen Mun	CEDD	27.8	0.00
6NW-C/C 204	Cut Slope	Lam Tei Evangelism School, Tuen Mun	Lands D	17.0	0.00
6NW-C/C 208	Cut Slope	Adjacent to License Land No. Y20561 GLL, Fok Hang Tsuen, Tuen Mun	Lands D	14.0	0.00
6NW-C/C 209	Cut Slope	Lam Tei Quarry, Tuen Mun	CEDD, Lands D, STT563	21.5	0.00
6NW-C/C 218	Cut Slope	House No. 170, Fuk Hang Tsuen, Lam Tei Quarry, Tuen Mun	Lands D	16.5	0.00
6NW-C/C 221	Cut Slope	Adj. to the downstream of Lam Tei reservoir, Lam Tei, Tuen Mun	Lands D	37.4	0.00
6NW-C/C 223	Cut Slope	SOUTH OF NAM ON TEMPLE, LAM TEI, TUEN MUN	Lands D	14.8	0.00
6NW-C/C 225	Cut Slope	Adjacent to and within License Land No. PM1049 GLL, Lam Tei, Tuen Mun	Lands D	18.5	0.00
6NW-C/C 226	Cut Slope	Nam On Temple, Lam Tei	Lands D	15.5	0.00
6NW-C/C 228	Cut Slope	East of Nam On Temple, Lam Tei, Tuen Mun	Lands D	21.0	0.00
6NW-C/C 229	Cut Slope	Adjacent to the Downstream of the Lam Tei Reservoir, Lam Tei.	Lands D	72.0	0.00
6NW-C/C 319	Cut Slope	Lam Tei Quarry, Tuen Mun	CEDD	22.6	0.00

Slope Number	Slope Type	Location	Maintenance Party	Maximum PPV (mm/s)	Maximum Shear Displacement (mm)
6NW-C/C 320	Cut Slope	Lam Tei Quarry, Tuen Mun	CEDD	95.5	0.01
6NW-C/C 330	Cut Slope	Lam Tei Quarry, Tuen Mun	CEDD	83.2	0.00
6NW-C/C 334	Cut Slope	Lam Tei Quarry, Tuen Mun	CEDD	117.9	0.08
6NW-C/C 337	Cut Slope	Lam Tei Quarry, Tuen Mun	CEDD	91.3	0.01
6NW-C/C 338	Cut Slope	Lam Tei Quarry, Tuen Mun	CEDD	90.2	0.01
6NW-C/C 339	Cut Slope	Lam Tei Quarry, Tuen Mun	CEDD	4.1	0.00
6NW-C/C 345	Cut Slope	Lam Tei Quarry, Tuen Mun	CEDD	82.2	0.00
6NW-C/C 346	Cut Slope	Lam Tei Quarry, Tuen Mun	CEDD	102.6	0.02
6NW-C/C 347	Cut Slope	Lam Tei Quarry, Tuen Mun	CEDD	133.3	0.19
6NW-C/C 348	Cut Slope	Lam Tei Quarry, Tuen Mun	CEDD	2.3	0.00
6NW-C/C 350	Cut Slope	Lam Tei Quarry, Tuen Mun	CEDD	96.3	0.01
6NW-C/C 351	Cut Slope	Lam Tei Quarry, Tuen Mun	CEDD	96.4	0.01
6NW-C/C 353	Cut Slope	Lam Tei Quarry, Tuen Mun	CEDD	117.8	0.08
6NW-C/C 354	Cut Slope	Lam Tei Quarry, Tuen Mun	CEDD	67.4	0.00
6NW-C/C 355	Cut Slope	Lam Tei Quarry, Tuen Mun	CEDD	116.3	0.07
6NW-C/C 356	Cut Slope	Lam Tei Quarry, Tuen Mun	CEDD	126.8	0.13
6NW-C/C 357	Cut Slope	Lam Tei Quarry, Tuen Mun	CEDD	143.6	0.31
6NW-C/C 362	Cut Slope	Lam Tei Quarry, Tuen Mun	CEDD	108.8	0.04
6NW-C/C 363	Cut Slope	Lam Tei Quarry, Tuen Mun	CEDD	2.4	0.00
6NW-C/C 369	Cut Slope	Lam Tei Quarry, Tuen Mun	CEDD	131.5	0.17
6NW-C/C 370	Cut Slope	Lam Tei Quarry, Tuen Mun	CEDD	138.5	0.25
6NW-C/CR 335	Cut Slope	No. 92 Fuk Hang Tsuen, Lam Tei, Tuen Mun	Lands D	48.0	0.00
6NW-C/F 115	Fill Slope	LAM TEI QUARRY, TUEN MUN	CEDD	19.8	0.00
6NW-C/F 119	Fill Slope	West of Lam Tei Quarry, Lam Tei, Tuen Mun	CEDD	5.8	0.00
6NW-C/F 198	Fill Slope	YUEN LONG HIGHWAY, HSR	HyD	13.3	0.00
6NW-C/F 203	Fill Slope	YUEN LONG HIGHWAY, HSR	HyD	20.8	0.00
6NW-C/F 204	Fill Slope	YUEN LONG HIGHWAY, HSR	HyD	14.4	0.00
6NW-C/F 222	Fill Slope	Lam Tei Quarry, Tuen Mun	CEDD	15.8	0.00
6NW-C/F 223	Fill Slope	Lam Tei Quarry, Tuen Mun	CEDD	91.3	0.01
6NW-C/F 227	Fill Slope	Lam Tei Quarry, Tuen Mun	CEDD	56.2	0.00
6NW-C/F 229	Fill Slope	Lam Tei Quarry, Tuen Mun	CEDD	15.6	0.00
6NW-C/FR 213	Fill Slope	Yuen Long Highway Main Chainage CH1973-CH2007	HyD	17.3	0.00
6NW-C/FR 219	Fill Slope	YUEN LONG HIGHWAY, HSR	HyD	23.9	0.00
6NW-C/FR 224	Fill Slope	House No.92, Lo Fu Hang, Lam Tei, Tuen Mun	Lands D	49.6	0.00
6NW-C/FR 225	Fill Slope	Near Lot No. 1028 sA in DD130 Near Nam On Temple, Lam Tei, Tuen Mun	DSD	1.8	0.00
6NW-C/R 63	Retaining Wall	FUK HANG TSUEN, NEAR FUK HANG TSUEN ROAD AND YUEN LONG HIGHWAY	CEDD	21.1	0.00
6NW-C/R 64	Retaining Wall	FUK HANG TSUEN, NEAR FUK HANG TSUEN ROAD AND YUEN LONG HIGHWAY	CEDD, Lands D	20.3	0.00
6NW-C/R 65	Retaining Wall	Lo Fu Hung, near Fu Tei Ha Tsuen, Tuen Mun	DSD	1.9	0.00
6NW-C/R 88	Retaining Wall	YUEN LONG HIGHWAY, SWC	HyD	32.5	0.00
6SE-C/C 34	Cut Slope	TUEN MUN ROAD, HSR	HyD	2.2	0.00
6SE-C/C 35	Cut Slope	TUEN MUN ROAD, HSR	HyD	2.0	0.00
6SE-C/C 232	Cut Slope	Tai Lam Chung Catchwater Section K CH 810 - 1040	WSD	1.5	0.00
6SE-C/C 519	Cut Slope	Adjoining WSD Catchwater near spot level 117.3	WSD	2.0	0.00
6SE-C/C 520	Cut Slope	Tai Lam Chung Catchwater Section K	WSD	1.8	0.00
6SE-C/C 533	Cut Slope	North of Hong Kong Garden, Tsing Lung Tau Sham Tseng, Tsuen Wan	DD388 LOT98 RP, DD388 LOT98 A, Lands D	2.4	0.00
6SE-C/C 534	Cut Slope	Hong Kong Garden, Tsing Lung Tau, N.T.	TLTL60B, Lands D	2.6	0.00
6SE-C/C 745	Cut Slope	Estoril Heights, Hong Kong Garden, Lung Tang Road, Tsing Lung Tau	TLTL60B	2.8	0.00
6SE-C/C 746	Cut Slope	Estoril Heights, Hong Kong Garden, Lung Tang Road, Tsing Lung Tau	TLTL60B	2.7	0.00
6SE-C/FR 33	Fill Slope	Sham Tseng Basin Catchwater (Southwest side)	WSD	2.1	0.00
6SE-C/ND 5	NT defence measures	Tai Lam Chung Catchwater Section K	HyD	1.9	0.00
6SE-C/ND 6	NT defence measures	Tai Lam Chung Catchwater Section K	HyD	1.9	0.00
6SW-A/C 250	Cut Slope	At Northern-east of Tseng Tau Tsuen Sheung Tsuen, Tuen Mun.	Lands D	8.8	0.00
6SW-A/C 251	Cut Slope	At Northern-east of Tseng Tau Tsuen Sheung Tsuen, Tuen Mun.	Lands D	9.2	0.00

Slope Number	Slope Type	Location	Maintenance Party	Maximum PPV (mm/s)	Maximum Shear Displacement (mm)
6SW-A/C 320	Cut Slope	CLP Pylon No 4CPF44 at Tai Lam Country Park, NT	CLP	11.0	0.00
6SW-B/C 247	Cut Slope	Adjoining WSD Access Road NT 22 near Spot Level 53.5	WSD	11.4	0.00
6SW-B/C 248	Cut Slope	Tai Lam Chung Catchwater Section H	WSD	39.8	0.00
6SW-B/C 249	Cut Slope	Tai Lam Chung Catchwater Section H	WSD	32.1	0.00
6SW-B/C 250	Cut Slope	Adjoining WSD Access Road NT 22 near Spot Level 44.9	WSD	5.9	0.00
6SW-B/CR 246	Cut Slope	Tai Lam Chung Catchwater Section H	WSD	25.2	0.00
6SW-B/F 92	Fill Slope	Tai Lam Chung Catchwater adjoining WSD Access Road NT 22	WSD	20.4	0.00
6SW-B/R 13	Retaining Wall	Maclehole Trail, South of Tai Lam Country Park	WSD	29.7	0.00
6SW-C/C 71	Cut Slope	Lo Tsing Shan, So Kwun Wat	Lands D	18.4	0.00
6SW-C/C 76	Cut Slope	Lo Tsing Shan, So Kwun Wat	Lands D	12.1	0.00
6SW-C/C 77	Cut Slope	28m North of So Kwun Wat Road, So Kwun Wat, Tuen Mun	GLL PM9, Lands D	14.1	0.00
6SW-C/C 99	Cut Slope	Adjacent to Water Supplies Department Access Road off So Kwun Wat Road, Tuen Mun	Lands D	6.7	0.00
6SW-C/C 144	Cut Slope	Adjacent to Water Supplies Department access road of So Kwun Wat Road, West of So Kwun Wat, Tuen Mun	Lands D	7.7	0.00
6SW-C/C 145	Cut Slope	So Kwun Wat, Tuen Mun.	Lands D	8.1	0.00
6SW-C/C 146	Cut Slope	So Kwun Wat, Tuen Mun	Lands D, DD374 Lot207	6.5	0.00
6SW-C/C 178	Cut Slope	About 34m North of License Land No. PM834, Tuen Mun Road, Siu Lam, Tuen Mun	Lands D	7.3	0.00
6SW-C/C 275	Cut Slope	Tai Lam Chung Catchwater Section H	WSD	57.1	0.00
6SW-C/C 279	Cut Slope	Tai Lam Chung Catchwater Section H	WSD	31.7	0.00
6SW-C/C 280	Cut Slope	Tai Lam Chung Catchwater Section H	WSD	63.3	0.00
6SW-C/C 281	Cut Slope	65M South-east of Chainage 2700, Maclehole Trail, Section 10, Castle Peak	Lands D	22.2	0.00
6SW-C/C 282	Cut Slope	Village House Located about 35m south of Chainage 2700. Catchwater Maclehole Trail, Tuen Mun	Lands D	33.3	0.00
6SW-C/C 283	Cut Slope	50m, south of CH 2850, catchwater, Maclehole Trail (Stage 10), Tuen Mun	Lands D	14.2	0.00
6SW-C/C 286	Cut Slope	50m Southwest of CH 2850, catchwater, MacLehose Trail (Stage 10), Tuen Mun	Lands D	19.5	0.00
6SW-C/C 287	Cut Slope	150M SOUTH OF CH250, CATCHWATER, MACLEHOSE TRAIL, TUEN MUN	PM1812, Lands D	11.8	0.00
6SW-C/C 288	Cut Slope	155 SE OF CH2850, CATCHWATER, MACLEHOSE TRAIL, TUEN MUN, 90 SO KWUN WAT TS	PM1812, Lands D	10.1	0.00
6SW-C/C 289	Cut Slope	70m SW of CH 2850, Catchwater, Maclehole Trail, Tuen Mun.	Lands D	19.2	0.00
6SW-C/C 290	Cut Slope	20m South West of Chainage 2960, Maclehole Trail, Tuen Mun.	Lands D	98.1	0.02
6SW-C/C 291	Cut Slope	Tai Lam Chung Catchwater Section H	WSD	42.1	0.00
6SW-C/C 313	Cut Slope	120m South of Chainage 3170, Catchwater, Maclehole Trail, Tuen Mun.	Lands D	8.3	0.00
6SW-C/C 314	Cut Slope	15m West of No. 90, So Kwun Wat Road, Tuen Mun	Lands D	8.2	0.00
6SW-C/C 315	Cut Slope	55m South of Chainage 3250, Catchwater, Maclehole Trail, Tuen Mun.	Lands D	15.5	0.00
6SW-C/C 316	Cut Slope	100m Southeast of Chainage 2850, Catchwater, Maclehole Trail, Tuen Mun.	Lands D	5.5	0.00
6SW-C/C 317	Cut Slope	20M SOUTHEAST OF CHAINAGE 3850, CATCHWATER, MACLEHOSE TRAIL, TUEN MUN	Lands D	30.1	0.00
6SW-C/C 318	Cut Slope	70m East of Lot 724 in DD374, So Kwun Wat, Tuen Mun	Lands D	26.3	0.00
6SW-C/C 319	Cut Slope	So Kwun Wat, Gold Coast	STT922, Lands D	23.0	0.00
6SW-C/C 320	Cut Slope	140m Southeast of Chainage 2850, Catchwater, Maclehole Trail, Tuen Mun	Lands D	7.7	0.00
6SW-C/C 321	Cut Slope	70m South of Chainage 2700, Maclehole Trail, Section 10, Tai Lam Country Park.	Lands D	26.3	0.00
6SW-C/C 322	Cut Slope	80m South of Chainage 2700, Maclehole Trail, Section 10, Castle Peak.	Lands D	21.6	0.00
6SW-C/C 324	Cut Slope	90m Southeast of Catchwater chainage 2700, Maclehole Trail, Section 10, Castle Peak	Lands D	17.6	0.00
6SW-C/C 325	Cut Slope	90m East of Chainage 2850, Maclehole Trail, Tuen Mun	Lands D	28.2	0.00
6SW-C/C 326	Cut Slope	110m Southeast of Catchwater Chainage 2700, Maclehole Trail, Section 10, Castle Peak	Lands D	16.3	0.00
6SW-C/C 330	Cut Slope	32m Northeast of Chainage 2700, Catchwater, Maclehole Trail, Tuen Mun	Lands D	26.7	0.00
6SW-C/C 331	Cut Slope	25m South of Chainage 2500, Catchwater, Maclehole Trail, Tuen Mun	Lands D	16.3	0.00
6SW-C/C 332	Cut Slope	35m South of Chainage 2500, Catchwater, Macle House Trail, Tuen Mun.	Lands D	13.9	0.00
6SW-C/C 335	Cut Slope	35m East of CH 2850, Catchwater, Maclehole Trail, Tuen Mun.	Lands D	40.6	0.00
6SW-C/C 336	Cut Slope	So Kwun Wat, Gold Coast	Lands D	23.0	0.00
6SW-C/C 337	Cut Slope	So Kwun Wat, Gold Coast	Lands D	23.6	0.00
6SW-C/C 338	Cut Slope	150m Southeast of Chainage 2850, Catchwater, Maclehole Trail, Tuen Mun.	Lands D	5.8	0.00
6SW-C/C 339	Cut Slope	So Kwun Wat, Tuen Mun	Lands D	13.5	0.00
6SW-C/C 891	Cut Slope	So Kwun Wat near Tai Lam Chung Catchwater	WSD	101.2	0.02
6SW-C/C 912	Cut Slope	So Kwun Wat, Tuen Mun (between Lamp Post BD4034 and VG0253)	Lands D	11.3	0.00
6SW-C/CR 67	Cut Slope	Tai Lam Chung Catchwater (Section H) Ch2135 - Ch2285	WSD	15.2	0.00
6SW-C/CR 272	Cut Slope	Tai Lam Chung Catchwater Section H	WSD	62.8	0.00

Slope Number	Slope Type	Location	Maintenance Party	Maximum PPV (mm/s)	Maximum Shear Displacement (mm)
6SW-C/CR 273	Cut Slope	Tai Lam Chung Catchwater Section H	WSD	66.3	0.00
6SW-C/CR 274	Cut Slope	Tai Lam Chung Catchwater Section H CH.2765-2850	WSD	60.0	0.00
6SW-C/CR 276	Cut Slope	Tai Lam Chung Catchwater Section H	WSD	71.2	0.00
6SW-C/CR 277	Cut Slope	Tai Lam Chung Catchwater Section H	WSD	84.3	0.00
6SW-C/CR 278	Cut Slope	Tai Lam Chung Catchwater Section H	WSD	24.3	0.00
6SW-C/CR 284	Cut Slope	Maclehose Traic	Lands D	16.1	0.00
6SW-C/CR 285	Cut Slope	20M SOUTH OF CH2850, CATCHWATER, MACLEHOSE TRAIL, TUEN MUN	Lands D	21.3	0.00
6SW-C/CR 292	Cut Slope	Tai Lam Chung Catchwater Section H	WSD	24.1	0.00
6SW-C/CR 293	Cut Slope	Tai Lam Chung Catchwater Section H	WSD	60.0	0.00
6SW-C/CR 294	Cut Slope	Tai Lam Chung Catchwater Section H	WSD	17.3	0.00
6SW-C/CR 334	Cut Slope	20m Southeast of CH 2850, Catchwater, Maclehose Trail, Tuen Mun	Lands D	33.0	0.00
6SW-C/F 33	Fill Slope	Tai Lam Chung Catchwater Section H	WSD	32.7	0.00
6SW-C/F 55	Fill Slope	Tai Lam Chung Catchwater Section H	WSD	16.1	0.00
6SW-C/F 57	Fill Slope	Tai Lam Chung Catchwater Section H	WSD	22.3	0.00
6SW-C/F 104	Fill Slope	Tai Lam Chung Catchwater Section H	WSD	8.7	0.00
6SW-C/F 106	Fill Slope	Tai Lam Chung Catchwater Section H Ch.3125 to Ch.3165, Tuen Mun	WSD	26.2	0.00
6SW-C/F 107	Fill Slope	Tai Lam Chung Catchwater - Section H & I, CH. 2800 to CH. 2900	WSD	26.4	0.00
6SW-C/F 109	Fill Slope	Tai Lam Chung Catchwater Section H	WSD	55.7	0.00
6SW-C/F 110	Fill Slope	Tai Lam Chung Catchwater Section H Ch.2700-2748	WSD	41.2	0.00
6SW-C/F 111	Fill Slope	Tai Lam Chung Catchwater Section H	WSD	37.2	0.00
6SW-C/F 112	Fill Slope	Below Maclehose Trail, Tuen Mun Section.	Lands D	18.8	0.00
6SW-C/F 113	Fill Slope	Below Maclehose Trail, Tuen Mun Section.	Lands D	9.5	0.00
6SW-C/FR 32	Fill Slope	Tai Lam Chung Catchwater Section H	WSD	105.0	0.03
6SW-C/FR 56	Fill Slope	Tai Lam Chung Catchwater Section H	WSD	24.5	0.00
6SW-C/FR 72	Fill Slope	Near Tuen Mun Road, So Kwun Wat	Lands D	6.9	0.00
6SW-C/FR 105	Fill Slope	Tai Lam Chung Catchwater Section H CH.3250 - 3295	WSD	16.0	0.00
6SW-C/R 47	Retaining Wall	South of Lot 724 in DD374, So Kwun Wat Village, Tuen Mun	Lands D	25.8	0.00
6SW-C/R 49	Retaining Wall	Near Lot 724 in DD374, So Kwun Wat Village, Tuen Mun	Lands D	32.8	0.00
6SW-D/C 2	Cut Slope	GLA No. TTW.607 Nearby	Lands D	48.6	0.00
6SW-D/C 3	Cut Slope	Castle Peak Road ԴÇô Tsing Lung Tau, Tsuen Wan	TLTL 70	16.4	0.00
6SW-D/C 19	Cut Slope	TUEN MUN ROAD, HSR	HyD	2.7	0.00
6SW-D/C 20	Cut Slope	TUEN MUN ROAD, HSR	HyD	4.1	0.00
6SW-D/C 21	Cut Slope	TUEN MUN ROAD, HSR	HyD	4.4	0.00
6SW-D/C 32	Cut Slope	Tai Lam Correctional Institution	CSD, Lands D	13.3	0.00
6SW-D/C 42	Cut Slope	TUEN MUN ROAD, HSR	HyD	2.2	0.00
6SW-D/C 43	Cut Slope	TUEN MUN ROAD, HSR	HyD	4.6	0.00
6SW-D/C 44	Cut Slope	TUEN MUN ROAD , HSR	HyD	93.3	0.01
6SW-D/C 45	Cut Slope	TUEN MUN ROAD , HSR	HyD	32.7	0.00
6SW-D/C 49	Cut Slope	TUEN MUN ROAD , HSR	HyD	6.0	0.00
6SW-D/C 50	Cut Slope	TUEN MUN ROAD , HSR	HyD	4.6	0.00
6SW-D/C 77	Cut Slope	TUEN MUN ROAD, HSR	HyD	4.1	0.00
6SW-D/C 79	Cut Slope	TUEN MUN ROAD, HSR	HyD	3.3	0.00
6SW-D/C 83	Cut Slope	TUEN MUN ROAD , HSR	HyD	4.4	0.00
6SW-D/C 85	Cut Slope	So Kwun Wat San Tsuen, Tuen Mun.	Lands D	4.5	0.00
6SW-D/C 86	Cut Slope	Tai Lam Chung Reservoir Access Road	WSD	5.2	0.00
6SW-D/C 87	Cut Slope	Adjoining WSD Access Road NT 21, Tuen Mun	WSD	5.7	0.00
6SW-D/C 88	Cut Slope	Tai Lam Chung Reservoir Access Road	WSD	6.0	0.00
6SW-D/C 89	Cut Slope	Wong Nai Tun Res Access Road	WSD	13.6	0.00
6SW-D/C 90	Cut Slope	Wong Nai Tun Res Access Road	WSD	20.1	0.00
6SW-D/C 91	Cut Slope	Tai Lam Catchwater (Sections H & I), near So Kwun Wat Road, Tuen Mun	WSD	21.6	0.00
6SW-D/C 93	Cut Slope	Tai Lam Chung Catchwater Section H	WSD	110.4	0.05
6SW-D/C 94	Cut Slope	Access Road Near To So Kwun Wat Tsuen, Tuen Mun.	Lands D	51.5	0.00
6SW-D/C 95	Cut Slope	Tai Lam Chung Catchwater Section H	WSD	11.3	0.00

Slope Number	Slope Type	Location	Maintenance Party	Maximum PPV (mm/s)	Maximum Shear Displacement (mm)
6SW-D/C 98	Cut Slope	So Kwan Wat Portable 'E', So Kwan Wat Road, Tuen Mun	WSD	10.7	0.00
6SW-D/C 113	Cut Slope	Tai Lam Chung Catchwater (Sections H & I), near So Kwun Wat Road, Tuen Mun	WSD	8.5	0.00
6SW-D/C 114	Cut Slope	Tai Lam Reservoir Access Road	WSD	5.5	0.00
6SW-D/C 115	Cut Slope	Between So Kwun Wat Tsuen & Pak Shek Hang.	Lands D	31.8	0.00
6SW-D/C 117	Cut Slope	So Kwun Wat San Tsuen, So Kwun Wat	Lands D	4.1	0.00
6SW-D/C 118	Cut Slope	Tai Lam Reservoir Access Road	WSD	5.5	0.00
6SW-D/C 120	Cut Slope	Tai Lam Chung Catchwater Section K	WSD	3.0	0.00
6SW-D/C 125	Cut Slope	Tai Lam Chung Catchwater Section K	WSD	2.1	0.00
6SW-D/C 139	Cut Slope	Tai Lam Chung Catchwater Section K	WSD	2.1	0.00
6SW-D/C 150	Cut Slope	Ka Loon Tsuen, Tsing Lung Tau, N.T.	Lands D	4.4	0.00
6SW-D/C 152	Cut Slope	Vistacove, Castle Peak Road, Tsing Lung Tau	DD388 LOT95RP, Lands D	10.3	0.00
6SW-D/C 153	Cut Slope	House Northwest of Bayside Villa, Tsing Lung Tau	Lands D	6.1	0.00
6SW-D/C 154	Cut Slope	House Northwest of Vista Cove, Tsing Lung Tau	Lands D	6.6	0.00
6SW-D/C 163	Cut Slope	Track, Tsing Lung Tau Storage Site, Water Service Department	HyD	39.3	0.00
6SW-D/C 170	Cut Slope	CASTLE PEAK ROAD - TSING LUNG TAU, TW	HyD	29.0	0.00
6SW-D/C 171	Cut Slope	Castle Peak Road - Tsing Lung Tau	Lands D	46.7	0.00
6SW-D/C 178	Cut Slope	GLA-TTW607 Access Road	HyD	20.5	0.00
6SW-D/C 179	Cut Slope	GLA NO. TTW.607 Access Road	HyD	31.0	0.00
6SW-D/C 180	Cut Slope	GLA NO. TTW.607 Access Road	HyD	60.6	0.00
6SW-D/C 181	Cut Slope	Access Road to Tsing Lung Tau Storage Site, WSD	Lands D	24.7	0.00
6SW-D/C 182	Cut Slope	Close to Access Road of Tsing Lung Tau Storage Site of WSD	Lands D	90.9	0.01
6SW-D/C 183	Cut Slope	Between Tuen Mun Road and Tsing Lung Tau Storage Site of WSD	Lands D	38.0	0.00
6SW-D/C 184	Cut Slope	Up slope of Dragon view, 128 Castle Peak Road.	Lands D	28.5	0.00
6SW-D/C 188	Cut Slope	TUEN MUN ROAD, HSR	HyD	115.7	0.07
6SW-D/C 212	Cut Slope	Within GLA - TM 437/MGS/74, Castle Peak Water Supply Tunnel, So Kwun Wat	WSD	3.4	0.00
6SW-D/C 222	Cut Slope	North of Siu Lam.	Lands D	4.9	0.00
6SW-D/C 223	Cut Slope	North of Siu Lam.	Lands D	4.2	0.00
6SW-D/C 224	Cut Slope	North of Siu Lam.	Lands D	3.3	0.00
6SW-D/C 225	Cut Slope	North of Siu Lam.	Lands D	3.0	0.00
6SW-D/C 237	Cut Slope	North of Siu Lam.	Lands D	3.5	0.00
6SW-D/C 256	Cut Slope	Adjoining Access Track within DD381	Lands D	3.9	0.00
6SW-D/C 271	Cut Slope	North West of Siu Lam Village.	Lands D	3.5	0.00
6SW-D/C 298	Cut Slope	North of Siu Lam Village, North of the Church, Tuen Mun.	Lands D	8.1	0.00
6SW-D/C 327	Cut Slope	No. 37 Siu Lam Tsuen, Siu Lam.	Lands D	7.6	0.00
6SW-D/C 378	Cut Slope	Downslope of catchwater, Tai Lam Country Park	Lands D	3.2	0.00
6SW-D/C 379	Cut Slope	Downslope of catchwater, Tam Lam Country Park	Lands D	3.8	0.00
6SW-D/C 380	Cut Slope	Tai Lam Chung Catchwater Section K	WSD	4.4	0.00
6SW-D/C 381	Cut Slope	200m east of catchwater No. 1700, northwest of Hong Kong Garden	Lands D	4.4	0.00
6SW-D/C 382	Cut Slope	South-East of Catchwater No. K1700, North -West of Hong Kong Garden	Lands D	4.1	0.00
6SW-D/C 385	Cut Slope	North of Choi Yuen Village, No.11A, Northwest of Hong Kong Garden, Tsuen Wan.	Lands D	9.9	0.00
6SW-D/C 386	Cut Slope	North West of 14A, 14mS Castle Peak Road, Choi Yuen Village, Tsing Lung Tau	Lands D, DD388 LOT 107	27.9	0.00
6SW-D/C 390	Cut Slope	No. 68B, Choi Yuen Tsuen, Tsing Lung Tau, N.T.	Lands D	30.4	0.00
6SW-D/C 392	Cut Slope	West of 4, Choi Yuen Village, Tsing Lung Tau, Tuen Mun.	LICENSE 2451, Lands D	26.6	0.00
6SW-D/C 393	Cut Slope	250m North of Choi Yuen Village No. 11 and northwest of Hong Kong Garden, Sham Tseng	Lands D	15.6	0.00
6SW-D/C 397	Cut Slope	Southeast of Choi Yuen Playground, Tuen Mun Road, Tsuen Wan	HyD, Lands D, TLTL 60 RP	18.7	0.00
6SW-D/C 398	Cut Slope	Northwest of Peony Heights, Tsuen Wan	Lands D	11.8	0.00
6SW-D/C 399	Cut Slope	North of Peony Heights, Tsuen Wan	TLTL60RP, Lands D	8.9	0.00
6SW-D/C 400	Cut Slope	Hong Kong Garden, Tsing Lung Tau	TLTL60RP, Lands D	8.3	0.00
6SW-D/C 401	Cut Slope	North of Peony Height, Hong Kong Garden, Tsing Lung Tau	Lands D, TLTL 60 RP	8.7	0.00
6SW-D/C 403	Cut Slope	WEST OF FONTANA HEIGHTS, HONG KONG GARDEN, TSING LUNG TAU	TLTL60B	3.5	0.00
6SW-D/C 404	Cut Slope	North Of Lincoln Heights, Hong Kong Garden, Tsing Lung Tau	TLTL60B, TLTL60RP	4.6	0.00
6SW-D/C 409	Cut Slope	TUEN MUN ROAD, HSR	HyD	99.6	0.02
6SW-D/C 410	Cut Slope	North of Choi Yuen Village No.11 and North west of Hong Kong Garden, Sham Tseng	Lands D	15.4	0.00

Slope Number	Slope Type	Location	Maintenance Party	Maximum PPV (mm/s)	Maximum Shear Displacement (mm)
6SW-D/C 411	Cut Slope	Northeast of Choi Yuen Village, No. 11 northwest of Hong Kong Garden	Lands D	13.3	0.00
6SW-D/C 412	Cut Slope	200m East of Choi Yuen Village No.11 and Northwest of Hong Kong Garden, Tsuen Wan	Lands D	12.1	0.00
6SW-D/C 413	Cut Slope	Northern Side of Tuen Mun Road	Lands D	9.9	0.00
6SW-D/C 415	Cut Slope	North-east of Choi Yuen Playground, Tsuen Wan	Lands D	11.4	0.00
6SW-D/C 416	Cut Slope	Northern side of Tuen Mun Road, near the Hong Kong Garden	Lands D	7.9	0.00
6SW-D/C 417	Cut Slope	West of 4A, 14MS Castle Peak Road, Choi Yuen Village, Tsing Lung Tau, Tuen Mun	Lands D	22.5	0.00
6SW-D/C 418	Cut Slope	Choi Yuen Village Tsing Lung Tau	GLL 9447, Lands D	14.0	0.00
6SW-D/C 419	Cut Slope	150 East of Choi Yuen Village No.11 and northwest of Hong Kong Garden, Tsing Lung Tau	Lands D	13.9	0.00
6SW-D/C 421	Cut Slope	850m North Western of Tuen Mun Road, Tsuen Wan	LICENCE 1243, Lands D	5.3	0.00
6SW-D/C 480	Cut Slope	Tai Lam Chung Catchwater Section J, Tuen Mun	WSD	9.9	0.00
6SW-D/C 481	Cut Slope	Tai Lam Chung Catchwater (Section J), Tuen Mun	WSD	19.0	0.00
6SW-D/C 482	Cut Slope	Tai Lam Chung Catchwater (Section J), Tuen Mun	WSD	22.7	0.00
6SW-D/C 483	Cut Slope	Tai Lam Chung C/W J Access Road, Tuen Mun	WSD	18.7	0.00
6SW-D/C 484	Cut Slope	Castle Peak Road, Tai Lam	Lands D	15.1	0.00
6SW-D/C 485	Cut Slope	Tai Lam Chung C/W J Access Road	WSD	21.3	0.00
6SW-D/C 486	Cut Slope	East of Tai Lam Chung Tsuen, near Castle Peak Road.	Lands D	61.5	0.00
6SW-D/C 487	Cut Slope	North of No.8 and 19, Tai Lam Chung Tseun, Tuen Mun.	DD385 LOT 27, DD385 LOT 30, Lands D	20.3	0.00
6SW-D/C 488	Cut Slope	Castle Peak Road, Tai Lam.	DD385 LOT 19, Lands D, DD385 LOT 20	17.3	0.00
6SW-D/C 504	Cut Slope	450m West of Tai Lam Correctional Institution, Tai Lam Chung, Tuen Mun	Lands D	13.7	0.00
6SW-D/C 505	Cut Slope	500m West of Tai Lam Correctional Institution, Tai Lam Chung, Tuen Mun.	Lands D	13.8	0.00
6SW-D/C 506	Cut Slope	450m West of Tai Lam Correctional Institution, Tai Lam Chung, Tuen Mun.	Lands D	18.6	0.00
6SW-D/C 510	Cut Slope	No.87-89 Tai Lam Chung Tsuen, Tuen Mun.	Lands D	12.5	0.00
6SW-D/C 529	Cut Slope	Tai Lam Chung Catchwater Section J	WSD	6.2	0.00
6SW-D/C 533	Cut Slope	Adjoining WSD Access Road NT 29, Tuen Mun	WSD	15.9	0.00
6SW-D/C 558	Cut Slope	Tai Lam Chung Reservoir Road, Tuen Mun	WSD	9.0	0.00
6SW-D/C 559	Cut Slope	Tai Lam Chung Reservoir Access Road	WSD	10.9	0.00
6SW-D/C 560	Cut Slope	Tai Lam Chung Reservoir Access Road	WSD	16.4	0.00
6SW-D/C 561	Cut Slope	Tai Lam Chung Reservoir Access Road	WSD	18.4	0.00
6SW-D/C 562	Cut Slope	Within GLA-TMTM/LM 87, Siu Lam	WSD	13.3	0.00
6SW-D/C 564	Cut Slope	West of No.2 Siu Lam San Village, Siu Lam.	Lands D	6.5	0.00
6SW-D/C 565	Cut Slope	No. 4 Siu Lam Village, Siu Lam, Tuen Mun	Lands D	6.1	0.00
6SW-D/C 566	Cut Slope	40M South West of No.3 Siu Lam Village, Siu Lam.	Lands D	5.4	0.00
6SW-D/C 573	Cut Slope	Siu Sau Village, Siu Lam, Tuen Mun.	Lands D	7.4	0.00
6SW-D/C 574	Cut Slope	No.1 Sau Siu Village, Siu Lam, Tuen Mun	Lands D	6.4	0.00
6SW-D/C 575	Cut Slope	North of House No. 2, Siu Lam Tsuen, Siu Lam, Tuen Mun	Lands D	6.4	0.00
6SW-D/C 576	Cut Slope	85m South of No. 2 Siu Lam, Tuen Mun	Lands D	11.1	0.00
6SW-D/C 577	Cut Slope	Southeast of No. 17-20 Rehab San Siu Lam Village, Siu Lam	WSD	13.1	0.00
6SW-D/C 578	Cut Slope	30m South of Nos. 17-19, Siu Lam Village, Siu Lam, Tuen Mun	Lands D	11.7	0.00
6SW-D/C 579	Cut Slope	75m South of No.17-19 Siu Lam Village, Siu Lam, Tuen Mun.	Lands D	13.9	0.00
6SW-D/C 580	Cut Slope	30MSE of No. 4 Siu Lam Village, Siu Lam	PM1857, Lands D	7.0	0.00
6SW-D/C 581	Cut Slope	90m Southeast of No. 4, Siu Lam Village, Siu Lam, Tuen Mun	Lands D	11.0	0.00
6SW-D/C 582	Cut Slope	Northwest of House No. 3, Siu Lam Tsuen, Siu Lam, Tuen Mun	Lands D	5.1	0.00
6SW-D/C 583	Cut Slope	20m West of No.3 Siu Lam Village, Siu Lam	Lands D	4.9	0.00
6SW-D/C 584	Cut Slope	Siu Lam Road, Siu Lam, Tuen Mun	Lands D	5.1	0.00
6SW-D/C 585	Cut Slope	No.3, Siu Lam Village, Siu Lam, Tuen Mun	Lands D	4.9	0.00
6SW-D/C 586	Cut Slope	55m Northeast of No. 3 Siu Lam Village, Siu Lam	Lands D	4.9	0.00
6SW-D/C 587	Cut Slope	Siu Lam, Castle Peak Road	Lands D	7.6	0.00
6SW-D/C 593	Cut Slope	65m South of No. 2 Siu Lam, Tuen Mun	Lands D	9.0	0.00
6SW-D/C 595	Cut Slope	Siu Lam Road, Siu Lam.	Lands D	7.0	0.00
6SW-D/C 596	Cut Slope	To the North of GLA-TMTM/LM78, Siu Lam	WSD	14.9	0.00
6SW-D/C 656	Cut Slope	Access Road to Siu Lam Tsuen, Siu Lam, Tuen Mun	Lands D	14.9	0.00
6SW-D/C 657	Cut Slope	Behind DD384, Lot PM5, Siu Lam Tsuen, Siu Lam, Tuen Mun	Lands D	32.9	0.00
6SW-D/C 658	Cut Slope	Siu Lam Tsuen, Siu Lam, Tuen Mun.	Lands D	31.3	0.00


Slope Number	Slope Type	Location	Maintenance Party	Maximum PPV (mm/s)	Maximum Shear Displacement (mm)
6SW-D/C 659	Cut Slope	NW of Lot 462 in DD384, Siu Lam Tsuen, Siu Lam, Tuen Mun	Lands D	38.7	0.00
6SW-D/C 660	Cut Slope	390m North of Hong Fai Road.	Lands D	39.5	0.00
6SW-D/C 661	Cut Slope	Within GLA-TM TMA59/2-D/F & Adjoining GL, Siu Lam, Tuen Mun	WSD	20.9	0.00
6SW-D/C 662	Cut Slope	Siu Lam Tsuen, Siu Lam	WSD	9.1	0.00
6SW-D/C 666	Cut Slope	Within GLA-TM TM/LM87 & Adjoining GL, Tuen Mun	WSD	19.5	0.00
6SW-D/C 667	Cut Slope	Within S Portion of GLA-TM TM/LM87 & Adjoining WSD Access Rd. NT24, Tuen Mun	WSD	20.7	0.00
6SW-D/C 669	Cut Slope	500m North of Hong Fai Road.	Lands D	17.8	0.00
6SW-D/C 670	Cut Slope	Below Service Reservoir of Siu Lam Staff Quarter, Siu Lam, Tuen Mun	Lands D	20.7	0.00
6SW-D/C 671	Cut Slope	Siu Lam Road, Siu Lam	Lands D	17.0	0.00
6SW-D/C 672	Cut Slope	Adjacent to Yuk Fai Terrace, Siu Lam Tsuen, Siu Lam, Tuen Mun	Lands D	19.2	0.00
6SW-D/C 676	Cut Slope	Siu Lam Village, Siu Lam.	Lands D	9.5	0.00
6SW-D/C 680	Cut Slope	Above Staff Quarters of Siu Lam Psychiatric Centre, Siu Lam, N.T.	Lands D	31.4	0.00
6SW-D/C 681	Cut Slope	Siu Lam Tsuen, Siu Lam, Tuen Mun	Lands D	12.6	0.00
6SW-D/C 685	Cut Slope	250 m North of Hong Fai Road, Siu Lam, Tuen Mun.	Lands D	16.7	0.00
6SW-D/C 686	Cut Slope	Siu Lam Tsuen, Siu Lam, Tuen Mun	Lands D	16.4	0.00
6SW-D/C 690	Cut Slope	Above Staff Quarter of Siu Lam Psychiatric Centre, Siu Lam, Tuen Mun	Lands D	18.5	0.00
6SW-D/C 691	Cut Slope	Above Staff Quarter of Siu Lam Psychiatric Centre, Siu Lam, Tuen Mun	Lands D	27.4	0.00
6SW-D/C 692	Cut Slope	Above Staff Quarters of Siu Lam Psychiatric Centre, Siu Lam, Tuen Mun.	Lands D	67.2	0.00
6SW-D/C 693	Cut Slope	Access Road to Siu Lam Tsuen, Siu Lam, Tuen Mun	Lands D	15.8	0.00
6SW-D/C 694	Cut Slope	Adjoining WSD Access Road NT24 Opposite DD384 Lot65, Tuen Mun	WSD	11.3	0.00
6SW-D/C 696	Cut Slope	Siu Lam Tsuen, Siu Lam	Lands D	21.1	0.00
6SW-D/C 697	Cut Slope	Access Road to Siu Lam Tsuen, Siu Lam	Lands D	19.0	0.00
6SW-D/C 698	Cut Slope	270m North of Hong Fai Road.	Lands D	22.2	0.00
6SW-D/C 699	Cut Slope	SIU LAM TSUEN, SIU LAM, TUEN MUN	Lands D	52.2	0.00
6SW-D/C 700	Cut Slope	Adjacent to Yuk Fai Terrace, Siu Lam Tsuen, Siu Lam.	Lands D	16.5	0.00
6SW-D/C 703	Cut Slope	Siu Lam Village, Siu Lam, Tuen Mun	Lands D	8.9	0.00
6SW-D/C 705	Cut Slope	Siu Lam Village, Siu Lam, Tuen Mun	Lands D	9.4	0.00
6SW-D/C 706	Cut Slope	No. 33A Siu Lam Village, Siu Lam, Tuen Mun	Lands D	8.9	0.00
6SW-D/C 708	Cut Slope	Siu Lam Tsuen, Siu Lam, Tuen Mun	Lands D	13.2	0.00
6SW-D/C 715	Cut Slope	Tai Lam Correctional Institution	CSD	16.7	0.00
6SW-D/C 716	Cut Slope	Tai Lam Correctional Institution, Tai Lam	CSD, WSD	21.3	0.00
6SW-D/C 717	Cut Slope	Tai Lam Correctional Institution, Tai Lam, Tuen Mun	WSD	27.1	0.00
6SW-D/C 718	Cut Slope	at TAI LAM CORRECTIONAL INSTITUTION, TAI LAM, TUEN MUN	CSD	16.7	0.00
6SW-D/C 720	Cut Slope	Adjoining WSD Access Road NT 24, Tuen Mun	WSD	11.5	0.00
6SW-D/C 721	Cut Slope	Tai Lam Chung Catchwater adjoining WSD Access Road NT 22, Tuen Mun	WSD	21.0	0.00
6SW-D/C 723	Cut Slope	Tai Lam Chung Catchwater adjoining WSD Access Road NT 22, Tuen Mun	WSD	5.1	0.00
6SW-D/C 724	Cut Slope	Tai Lam Chung Catchwater adjoining WSD Access Road NT 22, Tuen Mun	WSD	4.2	0.00
6SW-D/C 729	Cut Slope	Access road, So Kwun Wat, Tuen Mun	Lands D	3.8	0.00
6SW-D/C 730	Cut Slope	South of the Catchwater Access Road, So Kwun Wat, Tuen Mun.	Lands D	4.6	0.00
6SW-D/C 731	Cut Slope	South of the Dam Access Road, So Kwun Wat, N.T.	Lands D	5.2	0.00
6SW-D/C 732	Cut Slope	Half way up in the mountain, north to the dam access road, So Kwun Wat	Lands D	6.4	0.00
6SW-D/C 752	Cut Slope	Tai Lam Chung C/W Adjoining WSD Access Rd. NT22, Tai Lam	WSD	14.8	0.00
6SW-D/C 753	Cut Slope	So Kwun Tan, along So Kwun Wat Rd.	Lands D	13.8	0.00
6SW-D/C 754	Cut Slope	Tai Lam Chung Catchwater adjoining WSD Access Road NT 22, Tuen Mun	WSD	22.8	0.00
6SW-D/C 771	Cut Slope	Tai Lam Chung Catchwater adjoining WSD Access Road NT 22, Tuen Mun	WSD	5.7	0.00
6SW-D/C 773	Cut Slope	TUEN MUN ROAD, HSR(W1)	HyD	2.8	0.00
6SW-D/C 774	Cut Slope	TUEN MUN ROAD, HSR	HyD	3.3	0.00
6SW-D/C 779	Cut Slope	Hong Kong Garden, Tsing Lung Tau, N.T.	TLTL60RP	13.1	0.00
6SW-D/C 780	Cut Slope	Peony Heights, Hong Kong Garden, Tsing Lung Tau	TLTL60RP, Lands D	16.7	0.00
6SW-D/C 782	Cut Slope	TUEN MUN ROAD - Tsuen Wan , HSR(W1)	HyD	7.9	0.00
6SW-D/C 788	Cut Slope	Siu Lam Road, So Kwun Wat, Tuen Mun.	84 LOT37, DD384 LOT55, DD384 LOT36, Lan	13.3	0.00
6SW-D/C 798	Cut Slope	BEOW HOME FOR THE AGED, NEAR SIU LA, ROAD, SIU LAM	DSD	7.1	0.00
6SW-D/C 804	Cut Slope	NORTH OF HONG KONG GARDEN, NEAR TUEN MUN ROAD, TSING LUNG TAU	1243	5.3	0.00

Slope Number	Slope Type	Location	Maintenance Party	Maximum PPV (mm/s)	Maximum Shear Displacement (mm)
6SW-D/C 808	Cut Slope	75M NW OF BAYSIDE VILLAS, CASTLE PEAK ROAD - TSING LUNG TAU, TUEN MUN	Lands D	6.9	0.00
6SW-D/C 811	Cut Slope	350M, NORTH OF ORCHID HEIGHTS, HONG KONG GARDEN, TSING LUNG TAU, N.T.	1245	3.4	0.00
6SW-D/C 812	Cut Slope	Adjoining WSD Access Road NT34 and GLA TW250 Site B, near Choi Yuen Tsuen Village Supply Tank	WSD	8.1	0.00
6SW-D/C 813	Cut Slope	North of No.14 Ka Loon Village, Near Castle Peak Road, Tsing Lung Tau	Lands D	3.8	0.00
6SW-D/C 815	Cut Slope	80m North East of Grand Bay Villas, Castle Peak Road, Tsing Lung Tau, N.T.	HyD	22.0	0.00
6SW-D/C 821	Cut Slope	YUK FAI TERRACE, SIU LAM TSUEN, SIU LAM, TUEN MUN	DD384 LOT54, DD384 LOT55, DSD	16.3	0.00
6SW-D/C 823	Cut Slope	Tai Lam Correctional Institution	CSD, Lands D	25.8	0.00
6SW-D/C 825	Cut Slope	TSING LUNG TAU, TW	HyD	2.6	0.00
6SW-D/C 826	Cut Slope	CASTLE PEAK ROAD - TSING LUNG TAU, TW	HyD	7.1	0.00
6SW-D/C 829	Cut Slope	Behind House No. 15, Ka Loon Tsuen, Castle Peak Road, Tsing Lung Tau	Lands D	3.7	0.00
6SW-D/C 830	Cut Slope	70m NW of Grand Bay Villas, Castle Peak Road, Tsing Lung Tau	HyD	19.4	0.00
6SW-D/C 831	Cut Slope	30m NW of Grand Bay Villas Castle Peak Road, Tsing Lung Tau	HyD	30.3	0.00
6SW-D/C 832	Cut Slope	Area near Feature No. 6SW-D/C98, So Kwun Wat, Tuen Mun.	Lands D, WSD	8.4	0.00
6SW-D/C 834	Cut Slope	Near House No.8, Ka Loon Tsuen, Tsing Lung Tau	Lands D	4.0	0.00
6SW-D/C 835	Cut Slope	Near House Nos.12-13, Ka Loon Tsuen, Tsing Lung Tau	Lands D	4.7	0.00
6SW-D/C 836	Cut Slope	440m North of Siu Lam Hospital, Siu Lam, Tuen Mun	Lands D	25.1	0.00
6SW-D/C 843	Cut Slope	Unregistered Man-made feature near Lamp Post No. VD5387, Siu Lam Road	Lands D	16.1	0.00
6SW-D/C 846	Cut Slope	Castle Peak Road - Tsing Lung Tau, Tsuen Wan	TLTL 70	13.9	0.00
6SW-D/CR 92	Cut Slope	Tai Lam Chung Catchwater Section I & H CH595 - CH840	WSD	62.4	0.00
6SW-D/CR 96	Cut Slope	Tai Lam Chung Catchwater Section H	WSD	51.2	0.00
6SW-D/CR 97	Cut Slope	Tai Lam Chung Catchwater Section H	WSD	29.0	0.00
6SW-D/CR 99	Cut Slope	Tai Lam Chung Catchwater Section H	WSD	17.7	0.00
6SW-D/CR 121	Cut Slope	North of Catchwater Road	WSD	2.5	0.00
6SW-D/CR 124	Cut Slope	North Of Catchwater Road	WSD	2.1	0.00
6SW-D/CR 145	Cut Slope	Castle Peak Road - Tsing Lung Tau	STT710TW, STT711TW, HyD	9.1	0.00
6SW-D/CR 151	Cut Slope	BAY SIDE VILLA, CASTLE PEAK ROAD, TSING LUNG TAU, TSUEN WAN	DD388 Lot95RP	8.2	0.00
6SW-D/CR 156	Cut Slope	Behind House Nos. 12 13, Ka Loon Tsuen, Castle Peak Road, Tsing Lung Tau	Lands D	4.5	0.00
6SW-D/CR 158	Cut Slope	Plot 18 Ka Loon Tsuen, Castle Peak Road, Tsing Lung Tau	Lands D	4.1	0.00
6SW-D/CR 164	Cut Slope	Quarry Close to 128 Castle Peak Road	Lands D	63.0	0.00
6SW-D/CR 168	Cut Slope	Below Grand Bay Villas, 115 Castle Peak Road	DD388LOT97	17.0	0.00
6SW-D/CR 292	Cut Slope	House No. 6-7, Siu Lam Tsuen, Siu Lam, Tuen Mun	Lands D	6.9	0.00
6SW-D/CR 297	Cut Slope	Siu Lam Tsuen, Siu Lam, Tuen Mun	Lands D	7.4	0.00
6SW-D/CR 326	Cut Slope	Siu Lam Village, North of Church	Lands D, PM1925	7.6	0.00
6SW-D/CR 377	Cut Slope	Tai Lam Chung Catchwater Section K	WSD	3.9	0.00
6SW-D/CR 383	Cut Slope	Tai Lam Chung Catchwater Section K	WSD	6.5	0.00
6SW-D/CR 384	Cut Slope	Tai lam Chung Catchwater Section K Ch. 2000-2270	WSD	15.2	0.00
6SW-D/CR 387	Cut Slope	Tai Lam Chung Catchwater Section K Ch 2300-2386, Tsuen Wan	WSD	60.6	0.00
6SW-D/CR 388	Cut Slope	Tai Lam Chung Catchwater Section K	WSD	73.0	0.00
6SW-D/CR 389	Cut Slope	No. 68A, Choi Yuen Village, Tsing Lung Tau	Lands D	39.6	0.00
6SW-D/CR 402	Cut Slope	Hongkong Garden, Tsing Lung Tau, N.T.	TLTL 60 RP	7.6	0.00
6SW-D/CR 407	Cut Slope	North Of The Top Courser, Hong Kong Garden, Tsing Lung Tau	TLTL60RP	7.3	0.00
6SW-D/CR 508	Cut Slope	Castle Peak Road, Tai Lam, Tuen Mun	Lands D	16.6	0.00
6SW-D/CR 520	Cut Slope	Tai Lam Chung Catchwater Section J	WSD	4.2	0.00
6SW-D/CR 563	Cut Slope	West of Nos. 17-19, Siu Lam Village, Siu Lam, Tuen Mun	Lands D	8.9	0.00
6SW-D/CR 567	Cut Slope	North of No. 4, Siu Lam Village, Siu Lam, Tuen Mun	Lands D	5.8	0.00
6SW-D/CR 594	Cut Slope	60m South of No. 2 Siu Lam, Tuen Mun	Lands D	8.5	0.00
6SW-D/CR 597	Cut Slope	East of 4A, 14MS Castle Peak Road, Choi Yuen Village, Tsing Lung Tau	Lands D	24.0	0.00
6SW-D/CR 664	Cut Slope	Adjoining WSD Access Rd NT24, Tuen Mun	WSD	17.5	0.00
6SW-D/CR 668	Cut Slope	Yuk Fai Terrance, Siu Lam Tsuen, Siu Lam	Lands D	18.8	0.00
6SW-D/CR 673	Cut Slope	Yiu Fai Terrace, Siu Lam Tsuen, Siu Lam, Tuen Mun	Lands D	16.9	0.00
6SW-D/CR 674	Cut Slope	Siu Lam Village, Siu Lam, Tuen Mun	Lands D	10.7	0.00
6SW-D/CR 675	Cut Slope	House No. 44, Siu Lam Village, Siu Lam, Tuen Mun	Lands D	10.1	0.00
6SW-D/CR 701	Cut Slope	House No. 43, Siu Lam Village, Tuen Mun	Lands D	10.4	0.00





Slope Number	Slope Type	Location	Maintenance Party	Maximum PPV (mm/s)	Maximum Shear Displacement (mm)
6SW-D/CR 702	Cut Slope	Siu Lam Village, Siu Lam	Lands D	9.5	0.00
6SW-D/CR 704	Cut Slope	Siu Lam Village, Siu Lam, Tuen Mun.	Lands D	9.8	0.00
6SW-D/CR 786	Cut Slope	CASTLE PEAK ROAD - TSING LUNG TAU, TW	HyD	7.9	0.00
6SW-D/CR 796	Cut Slope	Tuen Mun Road - Tsuen Wan, HSR	HyD	2.6	0.00
6SW-D/CR 814	Cut Slope	North of No.11 Ka Loon Tsuen, Near Castle Peak Road, Tsing Lung Tau	Lands D	4.2	0.00
6SW-D/CR 827	Cut Slope	CASTLE PEAK ROAD - TSING LUNG TAU, TW	HyD	3.3	0.00
6SW-D/CR 828	Cut Slope	CASTLE PEAK ROAD - TSING LUNG TAU, TW	HyD	28.0	0.00
6SW-D/F 10	Fill Slope	Tuen Mun Road, HSR	HyD	5.8	0.00
6SW-D/F 11	Fill Slope	TUEN MUN ROAD , HSR	HyD	3.7	0.00
6SW-D/F 36	Fill Slope	Tai Lam Chung Catchwater Section K	WSD	47.0	0.00
6SW-D/F 66	Fill Slope	Tai Lam Chung Catchwater Section H	WSD	5.9	0.00
6SW-D/F 70	Fill Slope	Tai Lam Chung Catchwater Section H	WSD	107.3	0.04
6SW-D/F 73	Fill Slope	Tai Lam Chung Catchwater Section H	WSD	23.3	0.00
6SW-D/F 75	Fill Slope	Tai Lam Chung Catchwater Section K	WSD	2.1	0.00
6SW-D/F 76	Fill Slope	Tai Lam Chung Catchwater Section K	WSD	2.1	0.00
6SW-D/F 78	Fill Slope	Platform West of Abandoned Quarry near Tuen Mun Road, Tsing Lung Tau	HyD	13.6	0.00
6SW-D/F 83	Fill Slope	CASTLE PEAK ROAD - TSING LUNG TAU, TW	HyD	33.2	0.00
6SW-D/F 86	Fill Slope	TUEN MUN ROAD , HSR	HyD	7.9	0.00
6SW-D/F 87	Fill Slope	TGLA No. TTW607	Lands D	93.8	0.01
6SW-D/F 88	Fill Slope	GLA No. TTW.607	Lands D	134.6	0.20
6SW-D/F 89	Fill Slope	CASTLE PEAK ROAD - TSING LUNG TAU, TW	HyD	41.9	0.00
6SW-D/F 102	Fill Slope	East Side of Siu Lam Service Reservoir.	Lands D	2.8	0.00
6SW-D/F 111	Fill Slope	East of Grand View Terrace and North of Siu Lam Village ,Tuen Mun.	Lands D	4.1	0.00
6SW-D/F 136	Fill Slope	50m South of Chainage K1500 on catchwater, north of Choi Yuen, Tsing Lung Tau	LICENSE 1245, Lands D	3.3	0.00
6SW-D/F 137	Fill Slope	Tai Lam Chung Catchwater Section K	WSD	4.8	0.00
6SW-D/F 138	Fill Slope	Tai Lam Chung Catchwater Section K	WSD	8.1	0.00
6SW-D/F 140	Fill Slope	Tai Lam Chung Catchwater Section K CH.2350-2375	WSD	77.8	0.00
6SW-D/F 141	Fill Slope	170m Northwest of Peony Heights, Hong Kong Garden, Tsing Lung Tau	Lands D	12.8	0.00
6SW-D/F 142	Fill Slope	South of telegraph pole HKGB2 A17, South of CH K1600 on catchwater, North of Choi Yuen Village, Tsin	Lands D	3.7	0.00
6SW-D/F 143	Fill Slope	Tai Lam Chung Catchwater Section K	WSD	3.5	0.00
6SW-D/F 145	Fill Slope	North of Peony Height, Hong Kong Garden, Castle Peak Road	Lands D	10.8	0.00
6SW-D/F 146	Fill Slope	S OF WOODLAND HEIGHTS, HONG KONG GARDEN, TSING LUNG TAU	TLTL60RP	11.6	0.00
6SW-D/F 147	Fill Slope	Tai Lam Chung Catchwater Section K Ch.2200	WSD	30.7	0.00
6SW-D/F 149	Fill Slope	Tai Lam Chung Catchwater Section K	WSD	39.9	0.00
6SW-D/F 151	Fill Slope	TUEN MUN ROAD, HSR	HyD	11.8	0.00
6SW-D/F 153	Fill Slope	SOUTHEAST OF PEONY HEIGHTS, HONG KONG GARDEN, TSING LUNG TAU	TLTL60RP	7.9	0.00
6SW-D/F 155	Fill Slope	Government Land Near So Kwun Wat San Tsuen.	Lands D	4.0	0.00
6SW-D/F 186	Fill Slope	Near Tai Lam Chung Catchwater Section J C L 1000, Tai Lam Chung Tsuen, Tuen Mun	DD385 Lot156, Lands D	16.8	0.00
6SW-D/F 244	Fill Slope	Siu Lam Tsuen, Siu Lam, Tuen Mun	Lands D	34.1	0.00
6SW-D/F 253	Fill Slope	Access Road to Siu Lam Tsuen, Siu Lam.	Lands D	14.0	0.00
6SW-D/F 254	Fill Slope	Access Road to Siu Lam Tsuen, Siu Lam, Tuen Mun	Lands D	15.1	0.00
6SW-D/F 255	Fill Slope	50m South of Siu Lam Road ,Siu Lam Tuen Mun.	Lands D	24.6	0.00
6SW-D/F 256	Fill Slope	Siu Lam Tsuen, Siu Lam, Tuen Mun	Lands D	28.2	0.00
6SW-D/F 257	Fill Slope	Adjacent of Footpath, South of Tai Lam Chung Reservoir, Tai Lam Country Park	Lands D	18.8	0.00
6SW-D/F 260	Fill Slope	South of Catchwater Access Road, So Kwun Wat.	Lands D	4.1	0.00
6SW-D/F 261	Fill Slope	South of the Catchwater Access Road, So Kwun Wat, Tuen Mun.	DD378 Lot481, Lands D	3.7	0.00
6SW-D/F 262	Fill Slope	South of the Dam access road, So Kwun Wat, Tuen Mun.	Lands D	5.0	0.00
6SW-D/F 269	Fill Slope	TUEN MUN ROAD , HSR	WSD	80.9	0.00
6SW-D/F 292	Fill Slope	Tai Lam Correctional Institution along a Watercourse	CSD	14.2	0.00
6SW-D/F 299	Fill Slope	30M N OF ORCHID HEIGHTS, HONG KONG GARDEN, TSING LUNG TAU, TUEN MUN	LICENSE 1242, LICENSE 1243, Lands D	4.1	0.00
6SW-D/F 326	Fill Slope	40m NW of Grand Bay Villas Castle Peak Road, Tsing Lung Tau	HyD	31.9	0.00
6SW-D/F 329	Fill Slope	TUEN MUN ROAD , HSR	HyD	6.3	0.00
6SW-D/FR 6	Fill Slope	TUEN MUN ROAD , HSR(W1)	HyD	2.9	0.00


Slope Number	Slope Type	Location	Maintenance Party	Maximum PPV (mm/s)	Maximum Shear Displacement (mm)
6SW-D/FR 7	Fill Slope	TUEN MUN ROAD, HSR(W1)	HyD	2.7	0.00
6SW-D/FR 8	Fill Slope	TUEN MUN ROAD, HSR, HSR(W1)	HyD	10.0	0.00
6SW-D/FR 37	Fill Slope	Southeast of 4A, Choi Yeun Village, North of Hong Kong Garden, Tsing Lung Tau	DD388 LOT 107	27.6	0.00
6SW-D/FR 43	Fill Slope	GLA. TTW. 607 Access Road, Tsing Lung Tau	Lands D	142.1	0.29
6SW-D/FR 45	Fill Slope	TUEN MUN ROAD, HSR	HyD	2.9	0.00
6SW-D/FR 47	Fill Slope	TUEN MUN ROAD, HSR	HyD	9.0	0.00
6SW-D/FR 53	Fill Slope	Tai Lam Chung Catchwater Section H	WSD	94.1	0.01
6SW-D/FR 54	Fill Slope	Tai Lam Chung Catchwater Section H	WSD	14.3	0.00
6SW-D/FR 57	Fill Slope	Tai Lam Chung Catchwater Section H	WSD	13.6	0.00
6SW-D/FR 67	Fill Slope	Tai Lam Chung Catchwater Section H, Tuen Mun	WSD	12.8	0.00
6SW-D/FR 68	Fill Slope	Southern Side of Maclehoie Trail, Tuen Mun.	Lands D	122.5	0.10
6SW-D/FR 69	Fill Slope	Tai Lam Chung Catchwater Section H	WSD	63.1	0.00
6SW-D/FR 71	Fill Slope	Tai Lam Chung Catchwater Section H	WSD	58.1	0.00
6SW-D/FR 72	Fill Slope	Tai Lam Chung Catchwater Section H	WSD	43.0	0.00
6SW-D/FR 82	Fill Slope	CASTLE PEAK ROAD - TSING LUNG TAU, TW	HyD, DD388 LOT97	17.7	0.00
6SW-D/FR 135	Fill Slope	Tai Lam Chung Catchwater Section K	WSD	3.2	0.00
6SW-D/FR 144	Fill Slope	Tai Lam Chung Catchwater Section K	WSD	3.8	0.00
6SW-D/FR 148	Fill Slope	Tai Lam Chung Catchwater Section K	WSD	4.2	0.00
6SW-D/FR 150	Fill Slope	TUEN MUN ROAD, HSR	HyD	24.2	0.00
6SW-D/FR 152	Fill Slope	NW OF PEONY HEIGHTS, HONG KONG GARDEN, TSING LUNG TAU	TLTL60RP	8.4	0.00
6SW-D/FR 154	Fill Slope	South Of Manhattan Heights, Hong Kong Garden, Tsing Lung Tau	TLTL60RP	5.1	0.00
6SW-D/FR 264	Fill Slope	Access Road to Siu Lam Tsuen, Siu Lam, Tuen Mun	Lands D	29.2	0.00
6SW-D/FR 281	Fill Slope	Tuen Mun Road - Tsuen Wan, HSR	HyD	3.1	0.00
6SW-D/FR 286	Fill Slope	CASTLE PEAK ROAD - TSING LUNG TAU, TW	HyD	69.1	0.00
6SW-D/FR 312	Fill Slope	CASTLE PEAK ROAD - TAI LAM, TW	HyD	3.0	0.00
6SW-D/FR 314	Fill Slope	CASTLE PEAK ROAD - TSING LUNG TAU, TW	HyD	6.0	0.00
6SW-D/FR 315	Fill Slope	CASTLE PEAK ROAD - TSING LUNG TAU	HyD	5.6	0.00
6SW-D/FR 316	Fill Slope	East of Bayside Villa, Castle Peak Road, Tsuen Wan	HyD	15.7	0.00
6SW-D/FR 324	Fill Slope	West of Grand Bay Villas, Castle Peak Road, Tsing Lung Tau	HyD	12.5	0.00
6SW-D/FR 325	Fill Slope	CASTLE PEAK ROAD , TW	HyD	25.4	0.00
6SW-D/FR 327	Fill Slope	CATLE PEAK ROAD - TSING LUNG TAU, TW	HyD	15.1	0.00
6SW-D/FR 331	Fill Slope	TUEN MUN ROAD, HSR	HyD	92.5	0.01
6SW-D/ND 11	NT defence measures	Improvement to Tuen Mun Road - Tai Lam Section	HyD	2.8	0.00
6SW-D/ND 12	NT defence measures	Improvement to Tuen Mun Road - Tai Lam Section	HyD	3.3	0.00
6SW-D/ND 19	NT defence measures	Above Siu Lam Road, Tuen Mun	Lands D	52.3	0.00
6SW-D/ND 20	NT defence measures	Above Siu Lam Road, Tuen Mun	Lands D	57.5	0.00
6SW-D/ND 21	NT defence measures	Tuen Mun Road, HSR	HyD	3.7	0.00
6SW-D/ND 22	NT defence measures	Tuen Mun Road, HSR	HyD	3.7	0.00
6SW-D/ND 23	NT defence measures	East of Tennis Court near Block D, Tai Lam Correctional Institution, Tuen Mun	CSD	6.1	0.00
6SW-D/ND 26	NT defence measures	Above Siu Lam Road, Tuen Mun	Lands D	63.8	0.00
6SW-D/ND 27	NT defence measures	Castle Peak Road - Tsing Lung Tau, Tsuen Wan	TLTL 70	22.2	0.00
6SW-D/NS 7	NT stabilisation measures	East of Blocks D and E, Tai Lam Correctional Institution, Tuen Mun	CSD	6.7	0.00
6SW-D/NS 9	NT stabilisation measures	South of Tai Lam Correctional Institution, Tuen Mun	CSD	7.7	0.00
6SW-D/NS 11	NT stabilisation measures	Castle Peak Road - Tsing Lung Tau, Tsuen Wan	TLTL 70	12.1	0.00
6SW-D/NS 12	NT stabilisation measures	Castle Peak Road - Tsing Lung Tau, Tsuen Wan	TLTL 70	26.0	0.00
6SW-D/NS 13	NT stabilisation measures	Castle Peak Road - Tsing Lung Tau, Tsuen Wan	TLTL 70	22.8	0.00
6SW-D/NS 14	NT stabilisation measures	Castle Peak Road - Tsing Lung Tau, Tsuen Wan	TLTL 70	13.2	0.00
6SW-D/NS 15	NT stabilisation measures	Castle Peak Road - Tsing Lung Tau, Tsuen Wan	TLTL 70	13.2	0.00
6SW-D/NS 16	NT stabilisation measures	Castle Peak Road - Tsing Lung Tau, Tsuen Wan	TLTL 70	16.8	0.00
6SW-D/R 1	Retaining Wall	Castle Peak Road ΓÇô Tsing Lung Tau, Tsuen Wan	Lands D	18.2	0.00
6SW-D/R 2	Retaining Wall	Down Slope of Access to Tsing Lung Tau, WSD Storage Site	Lands D	101.9	0.02
6SW-D/R 5	Retaining Wall	Tai Lam Chung Catchwater Section H	WSD	28.2	0.00
6SW-D/R 6	Retaining Wall	Tai Lam Chung Catchwater Section H	WSD	21.1	0.00


Slope Number	Slope Type	Location	Maintenance Party	Maximum PPV (mm/s)	Maximum Shear Displacement (mm)
6SW-D/R 7	Retaining Wall	Tai Lam Chung Catchwater Section K	WSD	2.2	0.00
6SW-D/R 11	Retaining Wall	BAY SIDE VILLA, CASTLE PEAK ROAD, TSING LUNG TAU, TSUEN WAN	DD388 LOT95RP	8.8	0.00
6SW-D/R 12	Retaining Wall	House Northwest of Bayside Villa, Tsing Lung Tau	Lands D	5.6	0.00
6SW-D/R 13	Retaining Wall	Plot 15, Ka Loon Tsuen, Castle Peak Road, Tsing Lung Tau	Lands D	4.4	0.00
6SW-D/R 14	Retaining Wall	16, Ka Loon Tsuen, Tsing Lung Tau	Lands D	3.6	0.00
6SW-D/R 16	Retaining Wall	Castle Peak Road - Tsing Lung Tau	HyD	11.2	0.00
6SW-D/R 21	Retaining Wall	Access Road Entrance, Tsing Lung Tau Storage Site, Water Supplies Dept	Lands D	19.0	0.00
6SW-D/R 22	Retaining Wall	CASTLE PEAK ROAD - TSING LUNG TAU, TW	HyD	17.9	0.00
6SW-D/R 36	Retaining Wall	7m East of No. 37 Siu Lam Tsuen, Siu Lam	GLL PM2110, Lands D	8.1	0.00
6SW-D/R 48	Retaining Wall	E OF CULVERT MOUTH, NE OF FONTANA HEIGHTS, HONG KONG GARDEN, TSING LUNG TAU	TLTL60B	2.9	0.00
6SW-D/R 49	Retaining Wall	40m West Of Yale Villa, Hong Kong Garden Tsing Lung Tau	TLTL60RP	5.6	0.00
6SW-D/R 50	Retaining Wall	20M WEST OF YALE VILLA, HONG KONG GARDEN, TSING LUNG TAU	TLTL60RP	5.2	0.00
6SW-D/R 62	Retaining Wall	South of No.17-19 Siu Lam Village, Siu Lam.	Lands D	9.5	0.00
6SW-D/R 64	Retaining Wall	WEST OF CULVERT MOUNT, NE OF FONTANA HEIGHTS, HONG KONG GARDEN, TSING LUNG TAU	TLTL60B	3.0	0.00
6SW-D/R 65	Retaining Wall	50M East of Choi Yuen Village No. 11 and northwest of Hong Kong Garden	Lands D	14.9	0.00
6SW-D/R 72	Retaining Wall	Yuk Fai Terrace, Siu Lam Tsuen, Siu Lam	Lands D	14.6	0.00
6SW-D/R 74	Retaining Wall	Siu Lam Tsuen, Siu Lam, Tuen Mun.	Lands D	9.4	0.00
6SW-D/R 77	Retaining Wall	Siu Lam Tsuen, Siu Lam, Tuen Mun.	Lands D	8.6	0.00
6SW-D/R 95	Retaining Wall	East of No.13 Ka Loon Tsuen, Near Castle Peak Road, Tsing Lung Tau	Lands D	5.1	0.00
6SW-D/R 96	Retaining Wall	NORTH OF SIU LAM CHURCH, SIU LAM VILLAGE, SIU LAM	Lands D	8.0	0.00
6SW-D/R 99	Retaining Wall	580M NORTH EAST OF SO KWUN WAT TSUEN, SO KWUN WAT	Lands D	91.8	0.01
6SW-D/R 102	Retaining Wall	655M, NORTHEAST OF CUSTOMS & EXCISE TRAINING SCHOOL, TAI LAM CHUNG, TUEN MUN	WSD	8.2	0.00
6SW-D/R 106	Retaining Wall	CASTLE PEAK ROAD - TSING LUNG TAU, TW	HyD	3.4	0.00
6SW-D/R 107	Retaining Wall	CASTLE PEAK ROAD - TSING LUNG TAU, TW	HyD	3.7	0.00
6SW-D/R 108	Retaining Wall	CASTLE PEAK ROAD - TSING LUNG TAU, TW	HyD	4.3	0.00
6SW-D/R 109	Retaining Wall	CASTLE PEAK ROAD - TSING LUNG TAU, TW	HyD	8.0	0.00
6SW-D/R 110	Retaining Wall	TSING LUNG TAU, TW	HyD	3.5	0.00
6SW-D/R 111	Retaining Wall	TSING LUNG TAU, TW	HyD	8.1	0.00
6SW-D/R 112	Retaining Wall	CASTLE PEAK ROAD - TSING LUNG TAU, TW	HyD	4.8	0.00
6SW-D/R 113	Retaining Wall	CASTLE PEAK ROAD - TSING LUNG TAU, TW	HyD	5.5	0.00
6SW-D/R 130	Retaining Wall	35B, Siu Lam Village, Siu Lam.	GLL PM1892, Lands D	9.3	0.00
6SW-D/R 131	Retaining Wall	Castle Peak Road - Tsing Lung Tau, Tsuen Wan	Lands D	18.5	0.00
6SW-D/R 132	Retaining Wall	Castle Peak Road - Tsing Lung Tau, Tsuen Wan	TLTL 70	16.2	0.00



Legend

-  Geotechnical Features Considered
-  R11 Alignment
-  TMB Alignment
-  MagazineSite










Legend

- Geotechnical Features Considered
- R11 Alignment
- TMB Alignment
- MagazineSite





Legend

-  Geotechnical Features Considered
-  R11 Alignment
-  TMB Alignment
-  MagazineSite



6SWA/C 250
6SW2/C 251

6SWA/C 250

300

300

250

200

150

150

150

100

50

150

200

250

300

300

350

300

250

200

150

150

200

250

300

350

300

300

300

350

350

350





350





6SW-A/C
261

6SW-A/C
250





Legend

-  Geotechnical Features Considered
-  R11 Alignment
-  TMB Alignment
-  MagazineSite










Legend

-  Geotechnical Features Considered
-  R11 Alignment
-  TMB Alignment
-  MagazineSite






Legend

-  Geotechnical Features Considered
-  R11 Alignment
-  TMB Alignment
-  MagazineSite





香港黃金海岸第一期
 Hong Kong Gold Coast
 Phase 1

SO KWUN WAT


0 75 150 300
 Lepont
 Meters



Legend

-  Geotechnical Features Considered
-  R11 Alignment
-  TMB Alignment
-  Magazine Site





大欄涌
加氯房
Tai Lam Chung
Chlorination House

大欄涌
TAI LAM CHUNG

大欄涌村
Tai Lam Chung Tsuen

聯安新村
Luen On San Tsuen

露天貨倉
Open Storage


聯安新村
Luen On San Tsuen

大欄涌黃屋
Tai Lam Chung
Wong Uk





Legend

- Geotechnical Features Considered
- R11 Alignment
- TMB Alignment
- Magazine Site






Legend





-  Geotechnical Features Considered
-  R11 Alignment
-  TMB Alignment
-  MagazineSite








擲石
Kwai Shek

Legend

-  Geotechnical Features Considered
-  R11 Alignment
-  TMB Alignment
-  MagazineSite





馬灣咀
Ma Kok Tsui

馬灣漁民新村
(馬灣美徑環村)
Ma Wan Fishermen's Village
(Ma Wan CARE Village)

馬灣大街村
Ma Wan Main Street Village

MA WAN TOWN

拐石
Kwai Shek

公仔灣
KUNG TSAI WAN

倒扣灣
TO KAU WAN

五鼓嶺
NG KWU LENG

新舖咀
San Po Tsui

KAP SHUI M

青洲灣
TSING CHAU WAN





大青洲
Tai Tsing Chau

二軒
Yi Chuen

船廠 Shipyard

青洲仔
Tsing Chau Tsai

Legend

-  Geotechnical Features Considered
-  R11 Alignment
-  TMB Alignment
-  Magazine Site

