

Location / 位置	Lung Tsing Tau
Type / 種類	Abandoned House (Chan)
Map Ref. / 地圖參考檔號	#9
Arch. Assessment Ref. / 考古通參考檔號	TCR-01-2A12
AMO Ref. / 古物古蹟辦事處參考檔號	
Photographic Ref. / 照片參考檔號	#3029 (21)

Description / 說明	<p>L shaped structure - Various building fabrics - pounded earth, mud brick, cut stone, concrete. Right hand portion in ruins - collapsed roof on ground. Left hand side - courtyard terrace style - front portion open - rear portion roof intact - being used for storage - cut stone threshold, lintel and floor intact</p>
------------------	--

Photograph / 照片

