

Location / 位置	Lung Tsung Tau
Type / 種類	House (Chan)
Map Ref. / 地圖參考檔號	
Arch. Assessment Ref. / 考古通參考檔號	TCR-01-2314
AMO Ref. / 古物古蹟辦事處參考檔號	
Photographic Ref. / 照片參考檔號	#3029 (18)

Description / 說明	Abandoned single storey structure, mud brick with render. Tile roof - very overgrown. Walls collapsed in places at rear. 2 windows at rear. stone metal bars. Double panel wooden door in left hand unit.
------------------	--

Photograph / 照片

