



Noise Monitoring Station	Description	Use	No. of Floors
M5	Chuk Lam Ming Tong	Homes for the Aged	4

SCALE	DATE	DATE
A3 1:4000	11/11/05	DEC 07
CHECK	DRAWN	CCCM
DCFL	DCFL	CCCM
JOB No.	FIGURE No.	REV
60017198	3.1D	-

AGREEMENT NO. CE 43/2005 (EP)
 HARBOUR AREA TREATMENT SCHEME (HATS) STAGE 2A ENVIRONMENTAL IMPACT ASSESSMENT STUDY - INVESTIGATION
 LOCATION OF CONSTRUCTION NOISE MONITORING STATION - SANDY BAY PTW

