


Existing Condition

View northeast from the existing maintenance access along the northern riverbank of Sheung Yue River (VSR11 Pedestrians and Visitors of Sheung Yue Riverbank .



The visual quality of recreation users and residents from Ho Sheung Heung largely remains unchanged.

Day 1 of Operation Phase without landscape mitigation measures

View northeast from the existing maintenance access along the northern riverbank of Sheung Yue River .