



VSR 2 - LOOKING WEST FROM POK OI HOSPITAL: EXISTING CONDITIONS AT THE DEVELOPMENT SITE.



VIEW DISPLAYING THE 3D MODEL OF THE DEVELOPMENT SITE WITH LANDSCAPE AND VISUAL MITIGATION MEASURES AT DAY 1.



VIEW DISPLAYING THE 3D MODEL OF THE DEVELOPMENT SITE DAY 1 OF OPERATION WITHOUT LANDSCAPE AND VISUAL MITIGATION MEASURES



VIEW DISPLAYING THE 3D MODEL OF THE DEVELOPMENT SITE WITH LANDSCAPE AND VISUAL MITIGATION AT YEAR 10.




SUGGESTED SPECIES



NERIUM OLEANDER



SPATHODEA CAMPANULATA

 <p>Highways Department The Government of the Hong Kong Special Administrative Region</p>	<p>Consultant</p>  <p>Environmental Resources Management</p>  <p>Halcrow Halcrow China Ltd. As Engineering Sub-consultant</p>	<p>Agreement No. : WD 6/2007</p> <p>Project Title : Improvement to Pok Oi Interchange - Environmental Impact Assessment Study</p>	<p>Environmental Impact Assessment Report</p> <p>Photomontage from Visually Sensitive Receiver 2</p>	<p>Figure 8.8d</p> <table border="1"> <tr> <td>Checked</td> <td>PA</td> <td>Scale</td> <td>Rev.</td> </tr> <tr> <td>Designed</td> <td>SL</td> <td>Drawn</td> <td>AM</td> </tr> <tr> <td></td> <td></td> <td></td> <td>Date</td> </tr> <tr> <td></td> <td></td> <td></td> <td>07/01/2008</td> </tr> </table>	Checked	PA	Scale	Rev.	Designed	SL	Drawn	AM				Date				07/01/2008
Checked	PA	Scale	Rev.																	
Designed	SL	Drawn	AM																	
			Date																	
			07/01/2008																	