



VP2 – Existing conditions



VP2 – Photomontage at Day 1 of operation with no mitigation / enhancement

Figure 11.9a

Photomontage from VP2 – View from Lantau Trail, Stage 8
(Sheet 1 of 2)

DATE: 25/09//2017

Environmental
Resources
Management





VP2 – Photomontage at Day 1 of operation with mitigation / enhancement



VP2 – Photomontage at Year 10 of operation with mitigation / enhancement

Figure 11.9b

Photomontage from VP2 – View from Lantau Trail, Stage 8
(Sheet 2 of 2)

DATE: 25/09//2017