




Agreement No. CE 6/2019 (DS) Hung Shui Kiu Effluent Polishing Plant and Yuen Long South Effluent Polishing Plant – Investigation Timeseries Plots for Depth Averaged Dissolved Oxygen (mg/L) Blue: Normal Operation of YLSEPP (Scenario 1); Dashed Red: 2-hr Emergency Discharge from YLSEPP (Scenario 2)		Emergency	Dry Season
Appendix 5.6 – 01			
AECOM		/GPP/	emergency-d.ssn

Agreement No. CE 6/2019 (DS) Hung Shui Kiu Effluent Polishing Plant and Yuen Long South Effluent Polishing Plant – Investigation Timeseries Plots for Depth Averaged 5-Day Biochemical Oxygen Demand (mg/L) Blue: Normal Operation of YLSEPP (Scenario 1); Dashed Red: 2-hr Emergency Discharge from YLSEPP (Scenario 2)		Emergency	Dry Season
Appendix 5.6 – 02			
AECOM		/GPP/	emergency-d.ssn




Agreement No. CE 6/2019 (DS) Hung Shui Kiu Effluent Polishing Plant and Yuen Long South Effluent Polishing Plant – Investigation Timeseries Plots for Depth Averaged Total Inorganic Nitrogen (mg/L) Blue: Normal Operation of YLSEPP (Scenario 1); Dashed Red: 2-hr Emergency Discharge from YLSEPP (Scenario 2)	Emergency	Dry Season
	Appendix 5.6 – 03	
AECOM	/GPP/	emergency-d.ssn



Agreement No. CE 6/2019 (DS) Hung Shui Kiu Effluent Polishing Plant and Yuen Long South Effluent Polishing Plant – Investigation Timeseries Plots for Depth Averaged Unionised Ammonia (mg/L) Blue: Normal Operation of YLSEPP (Scenario 1); Dashed Red: 2-hr Emergency Discharge from YLSEPP (Scenario 2)	Emergency	Dry Season
	Appendix 5.6 – 04	
AECOM	/GPP/	emergency-d.ssn



Agreement No. CE 6/2019 (DS) Hung Shui Kiu Effluent Polishing Plant and Yuen Long South Effluent Polishing Plant – Investigation Timeseries Plots for Depth Averaged Total Nitrogen (mg/L) Blue: Normal Operation of YLSEPP (Scenario 1); Dashed Red: 2-hr Emergency Discharge from YLSEPP (Scenario 2)	Emergency	Dry Season
	Appendix 5.6 – 05	
AECOM	/GPP/	emergency-d.ssn



Agreement No. CE 6/2019 (DS) Hung Shui Kiu Effluent Polishing Plant and Yuen Long South Effluent Polishing Plant – Investigation Timeseries Plots for Depth Averaged Total Phosphorus (mg/L) Blue: Normal Operation of YLSEPP (Scenario 1); Dashed Red: 2-hr Emergency Discharge from YLSEPP (Scenario 2)	Emergency	Dry Season
	Appendix 5.6 – 06	
AECOM	/GPP/	emergency-d.ssn



Agreement No. CE 6/2019 (DS) Hung Shui Kiu Effluent Polishing Plant and Yuen Long South Effluent Polishing Plant – Investigation Timeseries Plots for Depth Averaged E.coli (count/100mL) Blue: Normal Operation of YLSEPP (Scenario 1); Dashed Red: 2-hr Emergency Discharge from YLSEPP (Scenario 2)	Emergency	Dry Season
	Appendix 5.6 – 07	
AECOM	/GPP/	emergency-d.ssn

Agreement No. CE 6/2019 (DS) Hung Shui Kiu Effluent Polishing Plant and Yuen Long South Effluent Polishing Plant – Investigation Timeseries Plots for Depth Averaged Suspended Solids (mg/L) Blue: Normal Operation of YLSEPP (Scenario 1); Dashed Red: 2-hr Emergency Discharge from YLSEPP (Scenario 2)	Emergency	Dry Season
	Appendix 5.6 – 08	
AECOM	/GPP/	emergency-d.ssn