

VP11 - ON PO TSUEN - EXISTING SITE CONDITION



PHOTOMONTAGE WITHOUT MITIGATION MEASURES





PHOTOMONTAGE WITH MITIGATION MEASURES AT YEAR 10



- 1. ALL DIMENSIONS ARE IN MILLIMETRES UNLESS OTHERWISE STATED.
- ALL LEVELS ARE IN METRES (M) AND RELATIVE TO HONG KONG PRINCIPAL DATUM (mPD).
- 3. FOR ILLUSTRATION ONLY. SUBJECT TO REVIEW.



AGREEMENT NO. CE 17/2021 (CE) TECHNICAL STUDY ON PARTIAL DEVELOPMENT
OF FANLING GOLF COURSE SITE - FEASIBILITY STUDY

PHOTOMONTAGE OF VIEWING POINT 11

| | Drawing no. FIGURE 11.10.11 | | | | Rev. |
|---|-----------------------------|----------|---------|----|---------|
| L | Drawn | Date | Checked | Ap | oproved |
| L | CAD | NOV 2021 | LW | | EW |
| L | Scale | • | Status | | |
| ı | N.T.S. | - | | | |

C COPYRIGHT RESERVED



土木工程拓展署
CIVIL ENGINEERING AND DEVELOPMENT
DEPARTMENT
北拓展處
NORTH DEVELOPMENT OFFICE