



ARUP 奥雅納工程顧問 Ove Arup & Partners Hong Kong Limited Crawing Tit


MAI Study Area and Geophysical Survey Area

gwing No.

Figure 12.1

HZMB – HKBCF & HKLR EIA Report

Image 24 Area not surveyed on the eastern shore of CLK Island, circled in red. [12-40]



HZMB – HKBCF & HKLR EIA Report

Image 27 Location of dive targets and transects

