

VP07 - NORTH DISTRICT PARK (EAST SIDE) **EXISTING CONDITION**



VP07 - NORTH DISTRICT PARK (EAST SIDE) DAY 1 WITH MITGATION MEASURES




VP07 - NORTH DISTRICT PARK (EAST SIDE) WITHOUT MITGATION MEASURES



VP07 - NORTH DISTRICT PARK (EAST SIDE) YEAR 10 WITH MITGATION MEASURES

MITIGATION MEASURES (CONSTRUCTION PHASE)						
CM1	Re-provisioned Cycle Track and Footpath	CM5	Good Site Practice			
CM2	Preservation of Existing Vegetation	CM6	Erection of Decorative Screen Hoarding			
CM3	Transplanting of Affected Trees	CM7	Reinstatement of Temporarily Disturbed Landscape Areas			
CM4	Control of Night-time Lighting Glare					

MITIG	MITIGATION MEASURES (OPERATION PHASE)				
0M1	Compensatory Tree Planting				
OM2	Roadside Planting				
0M3	Aesthetically pleasing design for carriageways and other highways structures				
0M4	Provision of Aesthetic Pleasing Treatment on Noise Barriers				



0	DRAFT ISSUE 1	BN	APR 22			
Rev	Description	Ву	Date			
Consultant						

AGREEMENT NO. CE 1/2021(HY)

IMPROVEMENT TO SO KWUN PO INTERCHANGE -INVESTIGATION, DESIGN AND CONSTRUCTION

PHOTOMONTAGE VIEWPOINT 07

FIGURE 9.8.7				0	
Drawn	Date APR 2022	Checked BN	Ap	proved CL	
Scale N.T.S		Status FOR INFORMATION			

© COPYRIGHT RESERVED

