





Baseline Condition - VP1 Sea Travellers



Development Without Mitigation - VP1 Sea Travellers





Development With Mitigation - VP1 Sea Travellers





Baseline Condition - VP2 Visitors at Tsang Tsui Columbarium (G/F Garden)





Development Without Mitigation - VP2 Visitors at Tsang Tsui Columbarium (G/F Garden)





Development With Mitigation - VP2 Visitors at Tsang Tsui Columbarium (G/F Garden)





Baseline Condition - VP3 Visitors at T-PARK (G/F Garden)





Development Without Mitigation - VP3 Visitors at T-PARK (G/F Garden)





Development With Mitigation - VP3 Visitors at T-PARK (G/F Garden)

Photomontages of Key Public Viewing Points | Appendix 9C

Remarks: The photomontages provide only aesthetic impression of the indicative form, size, and quality of the architectural and landscaping treatment for the structures. The final details of layout, materials, finishes will be subject to detailed design.





Baseline Condition - VP4 Travellers along Nim Wan Road





Development Without Mitigation - VP4 Travellers along Nim Wan Road





Development With Mitigation - VP4 Travellers along Nim Wan Road